

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-31488

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-9613

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
WEST DOLLARHIDE DRINKARD UNIT

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION

2. Name of Operator
TEXACO EXPLORATION AND PRODUCTION INC.

8. Well No.
121

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

9. Pool name or Wildcat
DOLLARHIDE TUBB DRINKARD

4. Well Location
Unit Letter E : 2176 Feet From The NORTH Line and 656 Feet From The WEST Line
Section 32 Township 24-SOUTH Range 38-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3150', KB-3163'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU SERVICE UNIT TIH TO PBTD OF 7452'. TESTED CASING TO 3000# FOR 30 MINUTES 07-18-93.
2. HLS RAN GR-CCL. PERFED w/ 2JSPF: 6894-96, 6899-6904, 6909-15, 6918-21, 6923-36, 6947-51, 6957-60, 6968-74, 7002-04, 7063-69, 7084-92, 7105-08, 7233-35, 7294-97, 7327-30, 7335-38. 144 HOLES.
3. DOWELL ACIDIZED WITH 6000 GAL 15% HCL. 07-20-93. SWAB 36 BLW AND 344 BW IN 12.5 HOURS 07-21-93.
4. TIH AND SET CIBP AT 6850'. CAPPED WITH 20' OF CEMENT. PBTD 6830'. TESTED CIBP TO 5000#.
5. PERFED WITH 2 JSPF: 6465-87, 6493-6505, 6516-34, 6550-54, 6560-65, 6570-74. 260 HOLES.
6. DOWELL ACIDIZED WITH 5000 GAL 15% HCL. 07-25-93. FLOWED 169 BLW AND 6 BW IN 18 HOURS 07-25-93.
7. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER AT 6444'. TESTED PACKER TO 560# FOR 30 MINUTES 07-27-93.
8. PREP FOR INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham / cwt TITLE DRILLING OPERATIONS MANAGER DATE 07-29-93

TYPE OR PRINT NAME C.P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 03 1993

CONDITIONS OF APPROVAL, IF ANY: