



5/7/97 - Fracture treated the Third Bone Spring Sand with 86,000 gals Medallion 3000 with 172,000# 16/30 Interprop.

5/10 through

5/13/97 - Snubbed 4-1/2" tubing out of the hole while flowing the well. Left packer in the hole. Released rig.

5/14/97 - Will continue to produce the well while evaluating packer retrieval options.

5/22/97 - 24 hrs Flow 234 MCF, 151 BO, 17/64" chk, 70 GP, 0 BLW, 42 LP.