State of New Mexico Form C-103 rals and Natural Resources Department Energy, N Revised 1-1-89 Submit 3 Copies to Appropriate WELL API NO. District Office OIL CONSERVATION DIVISION 30-025-31759 DISTRICT I P.O Box 2088 P.O. Box 1980, Hobbs, NM 88240 Indicate Type of Lease Santa Fe, New Mexico 87504-2008 DISTRICT II FEE X STATE P.O. Drawer DD, Artesia, NM 88210 6. State Oil & Gas Lease No DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) South Justis Unit "E" 1. Type of Well: OH. GAS other WELL. WELL 8. Well No. 2. Name of Operator 202 ARCO OIL and GAS COMPANY 3. Adress of Operator 9. Pool Name or Wildcat Justis Blinebry-Tubb-Dkrd P.O. Box 1610, Midland, Texas 79702 Well Locaztion 330 Feet from The Unit Letter E: 1450 Feet From The North Line and Line 37E **NMPM** County Section 24 Township 25S Range Lea 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3084 GR 11. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. CHANGE PLANS **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** (Other) (Other) 12. Describe Proposed or completed Operation Clearly state all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD'd 7-7/8 hole at 6050, 12-18-92. Ran OH logs. Ran 4-1/2 10.5# csg to 6050. DV tool at 3264. Core #1 f/5050-5165 Cmt'd w/350 sx PSL "C" w/6% gel + 3% salt (yld 2.0) followed by 300 sx "H" cmt w/8 pps CSE + #2 f/5165-5199 0.6% CF-14 + 0.35% thrifty lite. (1.61 yld). Open DV tool & circ 6 hrs. Did not circ cmt. Cmt'd #3 f/5199-5319 2nd stage W/1150 sx PSL "C" w/6% gel + 3% salt (yld 2.0) followed by 100 sx C Neat (yld 1.32). #4 f/5319-5429 Circ 82 sx to surf. RR 12-20-92. #5 f/5429-5549 #6 f/5549-5669 #7 f/5669-5783 #8 f/5783-5903 #9 f/5903-5956 1-17-93. RUPU. DO DV tool at 3264. Tag PBD 6009. Perf f/5048-5956. A 5672-5956 w/6000 gals. A 5359-5653 w/6000 gals. A 5048-5347 w/8000 gals. Ran CA: 2-3/8 tbg, rods & pump to 5945. RDPU 2-21-93. 2-26-93. In 24 hrs pmpd 35 BO, 23 BW, 63 MCF. 18 hereby certify that the information above is true and complete to the best of my knowledge and belief Regulatory Coordinator 3-2-93

(This space for State Use)

TYPE OR PRINT NAME

ORIGINAL SIGNED BY JERRY SEXTON

ENSTRUCT I SUPERVISOR

Ken W. Gosnell

TITLE

1000 0 4 1933

DATE

TELEPHONE

(915) 688-5672