

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31760
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name South Justis Unit "F"
8. Well No. 182
9. Pool name or Wildcat Justis Blbry-Tubb-Dkrd

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator P. O. Box 1610, Midland, Texas 79702
4. Well Location Unit Letter <u>N</u> : <u>1150</u> Feet From The <u>South</u> Line and <u>2550</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>25S</u> Range <u>37E</u> NMPM <u>Lea</u> County
5. Elevation (Show whether DF, RKB, RT, CR, etc.) 3071 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD'd 7-7/8 hole at 6075, 11-25-92. Ran OH logs.
Core #1 5154 - 5274 Ran 5-1/2 15.5# csq to 6075 w/DV tool at 3258.
#2 5274 - 5394 Cmt'd w/260 sx PSL "C" w/6% gel + gel + 3% salt (yld 2.0) followed
#3 5394 - 5510 by 220 sx "H" cmt w/8 pps CSE + 0.6% CF-14 + 0.35% thrifty lite (yld 1.6
#4 5510 - 5630 Open DV tool. Circ & WOC 6 hrs. Circ 90 sx cmt to surf. Cmt'd 2nd stage
#5 5630 - 5727 w/1550 sx PSL "C" w/6% gel + 3% salt (yld 2.0) followed by 100 sx "C"
#6 5727 - 5836 Neat.(yld 1.32). Circ 140 sx to surf. RR 11-28-92.
#7 5836 - 5956
#8 5956 - 6015 3-4-93. RUCU. Do DV tool. Tag at 6029 PBD. Perf f/4989-5965. 184 holes
A perfs 5330 - 5965 w/5000 gals. A perfs 5110 - 5285 w/7500 gals. A perfs 4989 - 5089
w/5000 gals. Left RBP at 5100. RIH w/CA: 2-3/8 tbg to 4993, rods & pump.

3-17-93. In 24 hrs pumped 2 BO, 3 BW, 16 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE Regulatory Coordinator DATE 3-17-93
TYPE OR PRINT NAME Ken W. Gosnell 915/688-5672 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNATURE BY JUDITH CEXTON

MAR 22 1993

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: