and the second s	_	÷ .				m		
Submit 3 Copies To Appropriate District Office State of New Lexico				Ť	,	Form C-103	•	
Enc. gy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 87240				WELL API 1	,	Revised March 25, 1999	\neg	
District II				W DDD THIT	.10.	30-025-31777		
811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION				5. Indicate 7	Type of L	ease		
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Lio Brazos Rd Aztec NM 87410			STAT	· · ·	FEE X		
District IV Santa Fe, NM 87505 2040 South Pacheco, Santa Fe, NM 87505				6. State Oi	l & Gas	Lease No.		
	TICES AND REPORTS ON	IWFIIS		7. Lease Na	me or Hi	nit Agreement Nam	e l	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:						NIT "E" WELL #17		
Oil Well Gas Well OtherWATER INJECTION WELL								
2. Name of Operator HENRY PETROLEUM LP					170			
3. Address of Operator 3525 ANDREWS HIGHWAY - SUITE 200					9. Pool name or Wildcat			
MIDLAND TX 79703-5000				JUSTIS-BLBRY-TUBB-DRINKARD				
4. Well Location								
Unit Letter_L	2300 feet from the	SOUTH	line and <u>330</u>	fe	et from t	he <u>WEST</u> li	ne	
Section 13	Township 25		nge 37-E	NMPM LE	<u>A C</u>	CountyNEW MEXI	СО	
	10. Elevation (Show wi	hether DR, F	RKB, RT, GR, etc.)			-		
	Appropriate Box to Inc	licate Na						
NOTICE OF II PERFORM REMEDIAL WORK	NTENTION TO: PLUG AND ABANDON	ı 🗆 📗	SUB REMEDIAL WOR	SEQUENT K		ORT OF: ALTERING CASING	€□	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DR	ILLING OPNS		PLUG AND ABANDONMENT		
PULL OR ALTER CASING [MULTIPLE COMPLETION		CASING TEST AND CEMENT JOBS					
OTHER:			OTHER:PERF. N				X	
 Describe proposed or completed of starting and proposed work 							iate	
or recompletion.	IK). SEE ROLE 1103, FOI I	with the C	ompletions. Attaci	i diagram or p	noposcu	Completion		
05/01/02 THRU 10/04/02: MIRU SU - PSI CASING TO 500# - OK - ND WH - REL. G-6 PKR INSTALL BOP - POOH W/IPC								
TUBING - TRIP IN HOLE W/BIT & TAG AT 5379' - SDON - CLEANED OUT FILL (IRON SULFIDE) FROM 5379' TO 5632' - CIRC HOLE CLEAN - POOH - LD BIT - SDON - SET CIBP AT 5585' & PERF. 5317'-5324', 5371'-5402' - ACIDIZE PERFS.								
W/3000 GALS - DISPLACED W. 170 BPW - POURED 28 SX SAND DOWN CASING - SDON - TRIP IN HOLE W/BIT - TAG SAND AT 5300' - RU GRAY SLICKLINE - TAGGED PBTD T 5286' - RD GRAY - RAN CEMENT RETAINER & SET AT								
5035' - CEMENTED WITH 50	SX 'C' - TAIL IN 150 SX 'C	C' - DRILI	LOUT CEMENT	RETAINER A	T 5035'	& CEMENT TO		
5100' - CIRC. HOLE CLEAN - 5280' - FELL OUT OF CEMEN							C	
TUBING - PUMPED 90 BBLS	PACKER FLLUID - SET P	ACKER -	PRESSURED TO	400# - TEST	OK - SE	T G-6 PACKER		
AND TUBIG AT 5300' - RAN NIN HOBBS.	MITTEST AT 400# FOR 3	30" - TEST	TED OK - SENT C	RIGINAL CH	IART &	C-103 TO NMOCO	j	
					$/\tilde{\kappa}$	line .		
					15	5 / 2003		
						Honne ED		
I hereby certify that the informa	tion above is true and comp	plete to the	best of my knowle	edge and belie	f. 📆	OCD S		
SIGNATURE Toy T.	Chuson		REGULATORY T	ЕСН.	16	DATE 01/24/2003	3	
Type or print nameROY R. JOH	INSON				Teleph	none No. (915)694-	<u>30</u> 00	
(This space for State use)								
APPROVED BY	A818	JAMIL BO	SNED BY			DATHAN 28	30a-	
Conditions of approval, if any:			NK DRECENTYTHE II	CTARE MANE	Kakh	- 		

