

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-31971

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

WEST DOLLARHIDE DRINKARD

8. Well No.

123

9. Pool Name or Wildcat

DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
P.O. Box 2100, Denver Colorado 80201

4. Well Location
Unit Letter M : 1275 Feet From The SOUTH Line and 200' Feet From The WEST Line
Section 32 Township 24-S Range 38-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRUSU. PULL RODS. NU BOP. TOH W/ TBG. 05-12-98.
2. RU KEY 96. SDI GYRO HOLE. TIW LUG. LUG @ 183 DEG. PU LATCH ASSEMBLY, DC. STAB. BLIND, SUB. DEBRIS SUB. SET WHIPSTOCK. BOTT @ 6249'. SLIDE: BOTT 6246' & TOP 6240'. TOH. 05-21-98.
3. MILL WINDOW 6239' TO 6246'. DRILL 4' FORMATION TO 6250'. 05-22-98.
4. TD LATERAL LEG # 1 @ 7239' MD. TOOH FOR WINDOW & WATERMELON MILLS. 05-25-98.
5. MILL WINDOW 6193' TO 6200' & 4' FORMATION TO 6204'. 05-26-98.
6. GYRO WHIPSTOCK & OPEN HOLE DIRECTION. GYRO CHECK SHOT @ 6227'. POOH. RUN IN HOLE W/STEER TOOL, SURVEY, LAND WET CONNECT. MAKE CONNECTION. 05-27-98.
7. LD 2 7/8" AOH DP. SI WELL. RIG REL @ 9:00 A.M. 05-30-98.
8. PU & TIH W/ BAKER RBP RETRIEVEING HEAD & 190 JTS 3 1/2" TBG TO 5896'. 06-01-98.
9. ACID FRAC'D EAST DRINKARD LATERAL DOWN 3-1/2" TBG W/60000 GALS 15% NEFE HCL & 7000 GALS WF 130 IN 8 EQUAL 15,000 GALS STAGES + 10000 GALS WF 130 FLUSH. 06-04-98.
10. RIH W/BAKER RBP & SET @ 6220'. RIH W/BAILER & DUMP 5' SAND ON RBP. 06-05-98.
11. DOWELL ACID FRAC'D WEST DRINKARD LATERAL DOWN 3-1/2" TBG W/60000 GALS 15% NEFE HCL & 70000 GALS WF 130 IN 8 20000 GALS STAGES & 10000 GAL WF 130 FLUSH. 06-09-98.
12. TOOH W/ 3 1/2" TBG. LAY ON RACKS. LAY DOWN 90 JTS. 06-11-98.
13. STARTED UP WELL @ 1500 HRS. 06-13-98.
14. OPT: PUMPED 327 BO, 576 BLW, 216 MCFD, FL 4672 IN 24 HOURS. 06-15-98.

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE C.P. Basham TITLE Eng. Assistant.

DATE 6/18/98

TYPE OR PRINT NAME Sheilla D. Reed-High

Telephone No. (303)793-4851

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE