

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-31998
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 133
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3207', KB-3220'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	4. Well Location Unit Letter O : 110 Feet From The SOUTH Line and 1330 Feet From The EAST Line Section 29 Township 24-SOUTH Range 38-EAST NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3207', KB-3220'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU SERVICE UNIT CLEANED OUT TO PBTD @ 7354'. TESTED CASING TO 3000# FOR 30 MINUTES 10-05-93.
2. HLS RAN GR-CCL FROM 7354' TO 6200'. PERFD WITH 2 JSPF: 6828-6840, 6852-6856, 6882-6891, 6896-6906, 6910-6916, 6950-6956, 6965-6970, 6995-7011, 7101-7104, 7112-7120, 7134-7148. 186 HOLES.
3. DOWELL ACIDIZED WITH 7000 GAL 15% HCL 10-08-93.
4. PERFD WITH 4 JSPF: 6578-6594, 6605-6626, 6633-6636, 6643-6648, 6664-6674, 6685-6691. 244 HOLES. TIH WITH RBP AND PACKER. SET RBP @ 6765'. SET PACKER @ 6750'. TEST RBP TO 5000#. RELEASE PACKER AND PULL UP HOLE TO 6298' AND SET.
5. DOWELL FRAC'D WITH 36000 GAL XLG WATER AND 29000# 20/40 SD. 10-12-93. TOH WITH PACKER & RBP.
6. TIH W/ 2 7/8 TUBING, RODS AND PUMP.
7. PUMPED 181 BO, 75 BW, 18 MCF IN 24 HRS. 10-25-93.
8. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / JKH TITLE DRILLING OPERATIONS MANAGER DATE 10-26-93
TYPE OR PRINT NAME C.P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ DATE NOV 01 1993
CONDITIONS OF APPROVAL, IF ANY: