Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

N.M. Oil Cons. Division 1625 N. Fre., ch Dr. Hobbs, NM 88240

FORM APPROVED

OMB No. 1004-0135 Expires November 30, 2000

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 5. Lease Serial No. NM-14215 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No.		
Type of Well								
☐ Oil Well ☐ Gas Well 🔯 Other						8. Well Name and No. SOUTH JUSTIS UNIT "10" #180		
2. Name of Operator HENRY PETROLEUM LP						9. API Well No.		
3a. Address 3b. Phone No. (include area code) 3525 ANDREWS HWY - MIDLAND TX 79703-5000 (915)694-3000						30-025-32079		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) UNIT LETTER P - 1050 FSL & 1050 FEL SEC. 14 - T25S - R37E						10. Field and Pool, or Exploratory Area JUSTIS-BLBRY-TUBB-DRINKARD  11. County or Parish, State LEA COUNTY		
12. CHECK AP	PROPRIATE BOX(ES) T	O INDICA	TE NATU	RE C	F NOTICE, R	EPORT, (	OR O	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION						·	
Notice of Intent	☐ Acidize	☐ Deeper	1		Production (Start	Resume)		Water Shut-Off
	Alter Casing		e Treat		Reclamation			Well Integrity
☐ Subsequent Report	Casing Repair		onstruction		Recomplete		X	Other WIW - ADD NEW PERFS - SQUEEZE
☐ Final Abandonment Notice			nd Abandon ack	_ •		rily Abandon isposal		OLD PERFS.
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandomment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  1) PULL OUT OF HOLE WITH DOWNHOLE WATER INJECTION EQUIPMENT.  2) RUN BIT & CLEAN OUT CASING TO 5730'.  3) RUN AND SET CIBP AT 5720'.  4) PERFORATE SELECTED INTERVALS FROM 5330-5515' - ACIDIZE PERFS. 5306-5515' W/3000 GALS 15% HCL.  5) SPOT SAND FROM 5720 TO 5300 - SET RET. AT 5050' AND CEMENT SQUEEZE PERFS.5111-5291' W/200 SX.  6) DRILL & CLEAN OUT RETAINER, CEMENT AND SAND TO 5520'.  7) RUN INJECTION PACKER AND IPC 2-3/8" TUBING & SET PACKER AT 5050'.  8) NOTIFY NMOCD AND PERFORM MIT & RETURN WELL BACK TO WATER INJECTION.								
( , , , , , , , , , , , , , , , , , , ,					ORY TECH.			A STO
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by				Title			Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				Office				
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or								

