

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32768
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	111
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3162'-GR, 3175'-KB	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location Unit Letter <u>K</u> : <u>1360</u> Feet From The <u>SOUTH</u> Line and <u>2055</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3162'-GR, 3175'-KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ REPERFORATING & ACIDIZING

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-22-97: MIRU. PMP STUCK. BACK OFF RDS. INSTL BOP.
10-23-97: TIH W/TBG TO 6900'. RAN CIBP TO 6580'.
10-24-97: MILL ON CSG FR 6580-6928'. CIRC CLN. RAN CIBP & SET @ 6850'. CAP PLUG W/35' OF CMT PLACING PBTD @ 6815'.
10-25-97: TIH W/PKR & RBP & TEST TBG W/5000 PSI ON TIH. SET RBP @ 6545' & SET PKR @ 6325'. A/DRINKARD W/3500 GALS 15% NEFE W/1200# RK SLT. AIR-5.2 BPM, AVG-1671, MAX-2317, MIN-1030, ISIP-1354, 15 MIN SIP 1133.
10-26-97: UNSET PKR & TIH & LATCH ONTO RBP. REL RBP & 40 JTS TBG.
10-28-97: PU MUD JT, SN, 1 JT TBG, 11 JTS 2 7/8" TBG, TAC, & 191 JTS 2 7/8" TBG. SN @ 6759'. TAC @ 6001'. BTM OF MUD JT @ 6792'. ND BOP & SET TAC. LD RDS. PU PUMP, GAS ANCHOR, SINKER BARS. SPACE OUT & LOAD & TEST. RD.
1-14-98: ON 24 HR OPT. PMPD 18 BO, 0 BW, 20 MCFPD. CHANGE STATUS FR WO TO PUMPING-OIL.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 1/16/98
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)
APPROVED BY GARY WINK TITLE FIELD REP. II DATE
CONDITIONS OF APPROVAL, IF ANY: