

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32770
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	149
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3126'-GL, 3141'-KB

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location  
Unit Letter M : 165 Feet From The SOUTH Line and 165 Feet From The WEST Line  
Section 32 Township 24-S Range 38-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3126'-GL, 3141'-KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU, POH rods & pump, install BOP. 3-26-96.
2. Run 5.5" RBP & PKR. Set RBP @ 6725'. Set PKR @ 6497'. Acidize Upper Abo perms 6508'-6697' w/4000 gal 15% NEFE, in 3 stgs w/ rock salts blocks. Rel PKR & RBP. Reset RBP @ 6495'. Set PKR @ 6020'. Acidize Tubb Drinkard perms 6044'-6495' w/6000 gal 15% NEFE in 4 stgs using rock salt blocks. 3-27-96.
3. Scale squeeze Tubb Drinkard perms 6044'-6495' w/ 2 drums Techni-Hib 793, flush w/400 bbls prod water. 3-28-96.
4. POH w/ PKR & RBP. RIH TBG W/TA. Remove BOP. 3-29-96.
5. Ran 10' GA, 2.5" x 1.5" x 24' pump, RD 3-30-96.
6. Testing on pump 3-31 thru 4-19-96.
7. MIRU, pull pump, install 10' GA, 2.5" x 1.75" x 22' pump, RD 4-20-96.
8. Testing on pump 4-21 thru 5-6-96.
9. OPT 51-BO, 246-BW, 45 MCF, 5-7-96.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Paula S. Ives TITLE Engineering Assistant DATE 6/11/96

TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE JUN 11, 1996

CONDITIONS OF APPROVAL, IF ANY: