

Submit 3 Copies
to Appropriate
District Office

DISTRICT I

PO Box 1980, Hobbs, NM 88241-1980

DISTRICT II

PO Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO
30-025-33507
5 Indicate Type of Lease
STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6 State Oil & Gas Lease No.
B-2317
7 Lease Name or Unit Agreement Name
Hale State
8 Well No
6
9 Pool name or Wildcat
Justis Blinbry

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101) FOR SUCH PROPOSALS.)	
1 Type of Well	
OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2 Name of Operator	
Primal Energy Corporation	
3 Address of Operator	
222 Pennbriht, #116, Houston, TX 77090	
4 Well Location	
Unit Letter <u>G</u> <u>2260</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line	
Section <u>2</u> Township <u>25S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
10 Elevation (Show whether DF, RKB, RT, GR, etc.)	
3,169' GL	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST & CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <input type="checkbox"/>	

12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103

1. Set CIBP at 5,900' on wireline. Test to 1000 psi.
2. Perforated Blinbry 2 SPF from 5444-46', 5460-62', 5530-40', 5560-62', 5591-95', 5606-08', 5621-27', 5634-36', and 5641-43'. (73 holes)
3. Frac'd with 108000 # 16/30 sand. Set RBP at 5400'. Perforated Blinbry 5090-5314'OA.
4. Frac'd with 80000# 16/30 sand, screened out.
5. Cleaned out well and recovered RBP at 5400'. Ran tubing, pump, and rods; made single completion in Blinbry.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Abernethy TITLE Manager, Operations & Engineering

DATE 12-13-96

TYPE OR PRINT NAME John Abernethy

TELEPHONE NO. 281-875-5100

(This space for State Use)

APPROVED BY _____

TITLE _____

DATE JAN 28 1997

CONDITIONS OF APPROVAL IF ANY

