

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33533
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	UNITED ROYALTY 'A'
8. Well No.	5
9. Pool Name or Wildcat	Dollarhide; Devonian

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>F</u> 1980 Feet From The <u>NORTH</u> Line and 1980 Feet From The <u>WEST</u> Line Section <u>19</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3183'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ evaluate

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-04-98: MIRU.
3-05-98: RDWH & RU BOP. TIAH W/BIT & CSG SCRAPER ON 2 7/8" TBG TO 5000'.
3-06-98: FINISH TIH TO 8993'. TIH W/ CMT RET ON 281 JTS 2 7/8" TBG TO 8912'. TEST TO 5000# PMP 51 BBLS & CLEAR RET. SET RET @ 8912'.
LOAD & TEST BACKSIDE TO 500# W/35 BFW.
3-07-98: SQUEEZE FUSSELMAN PERFS 8934-8976' W/50 SX 10-2 FRC. DUM 1/2 SK ON TOP OF RET & REV OUT.
3-09-98: TIH W/PERF GUN & PERF 8830-8836'. TIH W/PKR ON TBG TO 8756'.
3-10-98: BREAK CIRC & SPOT 84 GALS 15% NEFE HCL ACR PERFS 8830-8836'. PSA 8690'. BREAK DN PERFS @ .6 BPM @ 5130#.
3-11-98: SWAB FLUID LEVEL @ 6200'.
3-12-98: PMP 1000 GALS 15% MSR 100 ACID DN TBG. PMP ACID INTO DEVONIAN PERFS 8830-8836'.
3-13-98: TBG PRESS-90 PSI. BLED DN. RECVD GAS ONLY. SWAB - 20% OIL ON LAST SWAB RUN.
3-16-98: FL @ 6800'. SWAB DRY.
3-17-98: REL PKR & TOH W/TBG & PKR.
3-18-98: TIH W/CIBP & SET @ 8775'. PERF 8224-30, 8234-39, 8245-56. TIH W/PKR ON TBG TO 7835'.
3-19-98: TIH W/PKR & TBG TO 8255'. SPOT 84 GALS 15% NEFE HCL. PULL PKR TO 8151'. PSA 8151'. TEST BACKSIDE TO 500#-OK. ACIDIZE 8224-8256' W/1000 GALS 15% NEFE HCL. FL @ 3000'. RU NEW SWAB.
3-20-98: TBG PRESS-0 PSI. RECVD 0 BO, 45 BW, & SLIGHT ACID GAS. FL @ 500'. END FL @ 8150'. 0% OIL ON LAST RUN.
3-23-98: TBG PRESS-20 PSI. FL @ 7500'. END FL @ 8150'.
3-24-98: REL PKR. PERF FR 8256-8286'. RAN TP, PKR, & SN TO 8050'.
3-25-98: TP @ 8285'. SPOT 100 GALS ACID OVER PERFS. PULL TP TO 8151'. PSA 8088'. ACIDIZED 8224-8286' W/5000 GALS NEFE. SWABBING.
3-31-98: TBG PRESS-10 PSI. 1 SWAB RUN. RECVD TRACE OF OIL & 3 BW. FL @ 7300'. PULLED FLUID FR SN @ 8150'. 2% OIL ON THIS RUN.
REL PKR & TOH LD 2 7/8" TBG. REM BOP. SHUT IN W/TBG HANGER & VALVE. RIG DOWN. WORKOVER SUSPENDED - SI-OIL PENDING
EVALUATION.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 6/15/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

*This space for State Use

APPROVED BY Paul Koutz TITLE Geologist

DATE JUN 25 1998

CONDITIONS OF APPROVAL, IF ANY:

A
JUN 1998
Received
Hobbs
GPO

10579000