

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-33549	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. 14897	
7. Lease Name or Unit Agreement Name Bertha	
8. Well No. 5	
9. Pool name or Wildcat FOWLER TUBB, SOUTH	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Arch Petroleum, Inc.	
3. Address of Operator 10 Desta Drive, Suite 420E, Midland, Texas 79705	
4. Well Location Unit Letter M : 800 Feet From Th South Line and 990 Feet From The WEST Line Section 23 Township 24S Range 37E NMPM LEA County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3214' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON. ☐
CASING TEST AND CMT JOB ☐
OTHER: **Initial completion** ☒

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/22/97 MIRU Ram to squeeze off ABO perforations from 6302'-85' and 6403-08' with cement. Test tbg to 4,000#. Held ok.
Set 4-1/2" CIBP @ 6200', Dump 2 sacks cement on top of CIBP.
Perforate, acid treat, and frac from 5836' to 5935'.
6/6/97 Left well producing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE **PRODUCTION ANALYST** DATE: **6/26/97**
TYPE OR PRINT NAME **BOBBIE BROOKS** TELEPHONE NO **(915)685-1961**

APPROVED BY ORIGINAL SIGNED BY C. J. WILLIAMS
DISTRICT I SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY:

DATE