



EOG Resources, Inc.

August 6, 2001

NMOCD
1625 N. French Drive
Hobbs, New Mexico 88280
Attention: Donna Pitzer

Dear Donna,

As related to you in our telephone conversation this date, enclosed is a copy of your letter dated February 2, 1997 with handwritten notes by EOG's Dewey Smeltzer (Drilling Manager) and copy of Directional Survey performed by Schlumberger dated January 16, 1998.

Karen Sharpe requested information on 8-6-01 in telephone conversation with our David Frye.

Please advise if I can be of further assistance.

Yours very truly,

EOG RESOURCES, INC.

A handwritten signature in cursive script, appearing to read "Mike Francis".

Mike Francis

Enclosures



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

POST OFFICE BOX 1880
HOBBS NEW MEXICO 88241-1880
(505) 383-8181

February 2, 1999

Enron Oil & Gas Co
ATT: Dewey Smeltzer
P O Box 2267
Midland, TX 79702

RE: Greenback State 7 #1
Unit O, Sec, 7, T-24s, R-38e

Gentlemen:

We have received your tabulation of the directional survey and logs. According to OCD geologist Paul Kautz there are three different surveys and they do not agree as to where the bottomhole location is for the well listed above. We need the survey to show the correct bottomhole location. This will cause a delay in approving your C-104 request for allowable and authorization to transport for the well.

Please send the correct direction drill survey to the Oil Conservation Division - Hobbs office. If you have any question of this matter, please call (505) 393-6161 and speak to Paul Kautz at Ext. 104 or Donna Pitzer at Ext. 115.

Yours truly,

OIL CONSERVATION DIVISION

Chris Williams

Chris Williams
District I, Supervisor

CW:dp

2-8-99

cc I spoke with PAUL KAUTZ AND ADVISED him which
Survey he should be using.

2-10-99

I spoke with PAUL KAUTZ THIS AM HE ADVISED ME
THAT HE IS SATISFIED WITH THE SURVEY AND THE BH LOCATION.

WJD



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

POST OFFICE BOX 1880
HOBBS, NEW MEXICO 88241-1880
(505) 393-6161

February 2, 1999

Enron Oil & Gas Co
ATT: Dewey Smeltzer
P O Box 2267
Midland, TX 79702

RE: Greenback State 7 #1
Unit O, Sec, 7, T-24s, R-38e

Gentlemen:

We have received your tabulation of the directional survey and logs. According to OCD geologist Paul Kautz there are three different surveys and they do not agree as to where the bottomhole location is for the well listed above. We need the survey to show the correct bottomhole location. This will cause a delay in approving your C-104 request for allowable and authorization to transport for the well.

Please send the correct direction drill survey to the Oil Conservation Division - Hobbs office. If you have any question of this matter, please call (505) 393-6161 and speak to Paul Kautz at Ext. 104 or Donna Pitzer at Ext. 115.

Yours truly,

OIL CONSERVATION DIVISION

Chris Williams
District I, Supervisor

CW:dp

cc

8/3/01

Regulatory

Midland

David F. Pitzer

915 686 5764

Land
Dept. Greenback

686 3680

B.P.