

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
1625 N. French Dr.
Hobbs, NM 88240
APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER HORIZONTAL

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. PO BOX 3109, MIDLAND, TX 79702 915-688-475

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter I : 1650 Feet From The SOUTH Line and 940 Feet From The

EAST Line Section 26 Township 24-S Range 37-E

5. Lease Designation and Serial No.
NM14218

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
FRISTOE, C.C. 'B' NCT-2

23

9. API Well No.
30-025-34261

10. Field and Pool, Exploatory Area
JUSTIS TUBB DRINKARD

11. County or Parish, State
LEA, NM

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ OTHER: HORIZONTAL COMPLETION
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

2-22-01: MIRU PU. NDWH. NUBOP. 2-23-01: TAG CMT @ 4810. DRILL CMT & CIBP @ 4845. TAG CMT @ 5060. 2-24-01: DRILL CMT TO TOP OF CIBP @ 5095 & DRILL OUT CIBP. TIH W/2 3/8" TBG. TAG FILL @ 5642. 2-25-01: SET CMT RET. SQUEEZE GLORIETA PERFS 4900-4904 & BLINEBRY PERFS 5124-5522 W/200 SX CL H CMT & 100 SX CL H NEAT. REV OUT 32 SX CMT. 2-27-01: TAG CMT @ 4794. TAG CMT RET @ 4803. DRILL OUT CMT RET. 2-28-01: TAG RET @ 4805. DRILL GOOD CMT TO 4919. 3-01-01: DRILL CMT FR 4919-5172, 5235, 5256, 5298. TEST 1000 PSI. LOST 100 PSI IN 5 MIN FR 5298-5650 OPEN HOLE. TAG @ 5650. DRLG 5850-5705. RETURNS OF CMT & SAND. RETURNS OF PIECES OF CIBP & FRAC BALLS. DRILLED FR 5705-5705. 3-03-01: DRILL FR 5705-5710. 3-04-01: DRLG FRAC BALLS 5709-5752. DRLG CIBP @ 5752 TO 5760. OPEN HOLE FR 5760-5795. 3-05-01: DRLG PLUG FR 5760-6320 3-06-01: TIH W/CIBP & SET @ 5960. SHORT JT MARKER FR 5682-5702. 3-07-01: TAG CIBP @ 5950. (SLM) 10' CORRECTION FOR LOG DEPTH. TIH W/WHIPSTOCK. 3-08-01: MILL 5950-5951, 5955, 5958. TOW @ 5950, BOW @ 5955. DRILL 5958-5964, 5966, 5982, 6030, 6075, 6085, 6142, 6187, 6201, 6233, 6248, 6296, 6327, 6359, 6390, 6425, 6470, 6503, 6526, 6582, 6613, 6738, 6758, 6770, 6790, 6801, 6826, 6833, 6844, 6861, 6893, 6913, 6955, 6970, 7001, 7006, 7033, 7112, 7158, 7235, 7247, 7270, 7291, 7331, 7348, 7385, 7394, 7396, 7425, 7457, 7473, 7493, 7534, 7549, 7600. (3-16-01) 3-17-01: TIH W/FISHING TOOLS. TRY TO GET OVR TOP OF WHIP. MILL ON WHIPSTOCK FACE. 3-18-01: TIH W/RBP TO 5007 & SET PLUG. FLOW SHUT OFF. RIG RELEASED 1630 HRS ON 3-17-01. 3-24-01: TAG TOP OF FSH @ 5968. GO DN TO 5983. RECVD SHOE. 3-25-01: TIH W/TAP, BMPR SUB, JAR, X-OVER, WS. WRK FR 5950-5960. 3-27-01: PU SUB, X-OVER, SN @ 5844 & 2 7/8" TBG. SET PKR W/20,000 COMPRESSION. 4-01-01: ACID FRAC DRINKARD OPEN HOLE LATERAL 5958-7600 W/40,000 GALS 15% HCL & 10,000 GALS WF-110 4-03-01: RIJ SWAB. 4-05-01: REL PKR. 4-07-01: SET TAC @ 5882. SN @ 5914. PU PMP, GA, K-BARS, & RDS. WELL ON PRODUCTION @ 10 AM 4-07-01. PUMPING & TESTING.

4-17-01: ON 24 HR OPT. PUMPING 28 BO, 160 BW, & 127 MCF.

(CIBP @ 5960', TOW @ 5950, BOW @ 5955, RBP @ 5007'.)

FINAL REPORT

14. I hereby certify that the foregoing is true and correct.

SIGNATURE *J. Denise Leake* TITLE Engineering Assistant

TYPE OR PRINT NAME J. Denise Leake

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: TITLE DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

28 Justis Glorietta

