Submit 3 Copies to Appropriate District Offices	State of Energy, Minerals and		urces Departm	ent	Form C-103 Revised 1-1-8	89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240 DISTRICT II	OIL CONSERVATION DIVISION 310 Old Santa Fe Trail, Room 206 Santa Fe, New Mexico 87503			WELL API NO. 30-025-3511		
P.O. Drawer DD, Artesia, NM 88210				5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.		FEE	
				B-9613		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name West Dollarhide Queen Unit		
1. Type of Well: OIL WELL GAS WELL	, OTHER					
2. Name of Operator Saga Petroleum LLC				8. Well No. 156	· · · · · · · · · · · · · · · · · · ·	
3. Address of Operator 415 W Wall, Suite 1900, Midlan	nd, TX 79701	·····		9. Pool name or Wildcat Doliarhide Queen		
4. Well Location Unit Letter <u>M</u> :1104	Feet From The	ГН	Line and 915	Feet Fro	om The WEST	_ Line
Section 32	Township 24S	Range 3	8E	NMPM LEA		County
	10. Elevation (2 3147'	Show whether DF,	RKB, RT, GR, etc.)			
11. Check A		1	· -			
NOTICE OF INT ERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ	COMM CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfac	SUB DIAL WORK MENCE DRILLING IG TEST AND CE R: and give pertinent a 8-5/8" 24# Ce.	OPNS. X	REPORT OF: ALTERING CASING PLUG AND ABANDON mated date of starting any p	[
NOTICE OF INT ERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r	Comm CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx	OPNS. X	ALTERING CASING PLUG AND ABANDON	[
NOTICE OF INT ERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r	Comm CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx	OPNS. X	ALTERING CASING PLUG AND ABANDON	
NOTICE OF INT ERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state all ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r ed @ 7:30 PM 10-21-20	COMM CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp 000.	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx	a OPNS. X MENT JOB X	ALTERING CASING PLUG AND ABANDON	proposed
NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER:	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r ed @ 7:30 PM 10-21-20 we and complete to the best of my k	COMM CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp 000.	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx survey	a OPNS. X MENT JOB X lates, including estin	ALTERING CASING PLUG AND ABANDON mated date of starting any p	proposed
NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER:	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r ed @ 7:30 PM 10-21-20 we and complete to the best of my k	COMM CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp 000.	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx survey	a OPNS. X MENT JOB X lates, including estin	ALTERING CASING PLUG AND ABANDON mated date of starting any p	proposed
NOTICE OF INT ERFORM REMEDIAL WORK EMPORARILY ABANDON ULL OR ALTER CASING THER:	TENTION TO: PLUG AND ABANDON CHANGE PLANS erations (Clearly state al ole @ 7:30 PM 10-11-2 260 sx Prem Plus, circ ed core pt @ 3:30 AM 1 s 5-1/2" 14# J55 csg to 0 sx Class C. Cmt did r ed @ 7:30 PM 10-21-20 we and complete to the best of my k	COMM CASIN CASIN OTHE Upertinent details, 000. Ran 9 jts 73 sx to surfact 0-18-2000, co 3784'. Cmt w/ not circ -Temp 000.	SUB DIAL WORK MENCE DRILLING IG TEST AND CEL R: and give pertinent of 8-5/8" 24# ce. red to 3605', 1300 sx survey	a OPNS. X MENT JOB X lates, including estin	ALTERING CASING PLUG AND ABANDON mated date of starting any p	proposed