					N.M. Oil Cons. Division 1625 N. French Dr.		
Form 3160-5						SINM 88240 PPROVED	
(August 1999)		EPARTMENT OF THE	INTERIOR			Exp	MB No. 1004-0135 res November 30,2000
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for porposals to drill or to re-enter an						5 Lease Serial No	
						LC-061	
		ell. Use Form 3160-3 (A				6. If Indian, 7	Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other Instructions on reverse side						<ol> <li>If Unit or CA/Agreement, Name a No.</li> <li>8. Well Name and No.</li> </ol>	
Type of Well     Gas Well     Gas Well     Other     DRY HOLE							
2. Name of Operator Sahara Operating Company						Spencer Federa 51	
3a Address	3b. Phone No. <i>(include area code)</i>			9. API Well No.			
P.O. Box 4130,	, Midland	I, TX 79704				30-025 -35390 10. Field and Pool, or Exploratory Arr	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						Paduca Delaware	
Unit Letter M, 478' FSL & 680' FWL, Section 5, T-25-S; R-32-E						11. County or Parish, State	
						Lea cou	unty, N.M.
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,						REPORT, OR OTHER DATA	
TYPE OF SUBMIS	SION			TYPE OF			
Notice of Intent			Deepen		_	m (Start Resume)	Water Shut-Off
_		Alter Casing	New Construction		Reclamat		
Subsequent Report		Casing Repair			Recompl	emporarily Abandon	
Final Abandonment M	Notice	Convert to Injection	Plug Back	luon	Water Di		
3-7-01	all be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final insp TIH w/OEDP, set (a) 4628'. RU BJ, pmp 200 sx class C, pull 20 stands, WOC 4 hrs.						
	TIH, tag plug @ 4184'. Pull drill pipe.						
3-801	Set OEDP @ 790'. BJ mix & pmp 85 sx Class C. POOH. WOC. TBIH & tag cmt						
	(a) 643'. LDDP. Set DP (a) 63' (50 ' below surface, 13' KI					B correction	n) - Mix & Pum
	15 sx, cmt circ. POH. ND BOP, cut off WH & csg @ btm of co						Well P&A
	Plugging witnessed by Mr. Marlon Deaton, BLM Hobbs						
	Will	install DH marker af	ter rig moves	1.	and the marine	to plugging of bond is retain aftica is cutagi	ieg wann
<ul> <li>14. 1 hereby certify that Name (<i>Printed Type</i>)</li> </ul>		ping is true and correct					
Name (Printed Type		C		Title	Presiden		
Name (Printed Type Rob	ed)	C			Presiden March 9,		
Name (Printed Type	ed)	Alpine Alpine	m	Date	March 9,	2001	
Name (Printed Type Robe Signature	ed) ert Mc A	Alpine Alpine THIS SPACE FO		Date	March 9,	2001	
Name (Printed Type Robe Signature	ed) ert Mc A	Alpine Alpine	}	Date	March 9, OFFICE US	2001 E	
Name (Printed Type Robe Signature	ert Mc A	Alpine Alpine THIS SPACE FO	<b>}</b>	Date DR STATE	March 9,	2001 E	Date MAR 13

50

## •

entre de la constante de la co

Area Filler