· · · · · · · · · · · · · · · · · · ·	ם:	1			· F (2 100
DISTRIBUTION					Form (sedes Old
SANTA FE		⊢ NF	W MEXICO OIL CON	SERVATION COMMISSION	C-102	and C-103
FILE			IN MEXICO OIL CON	SERVATION COMMISSION	Effect	tive 1-1-65
U.S.G.S.					5g. Indica	tte Type of Lease
LAND OFFICE					State	
OPERATOR		_			<u> </u>	Oil & Gas Lease No.
						
(DO NOT USE TH	SUN S FORM FOR USE "APPLI	DRY NOTICES PROPOSALS TO DRILL CATION FOR PERMIT	AND REPORTS ON	WELLS BACK TO A DIFFERENT RESERVOIR CH PROPOSALS.)		
			<u> </u>	111110100223.7		greement Name
OIL WELL	GAS WELL	OTHER- 117				• · · · · · · · · · · · · · · · · · · ·
2. Name of Operator		T ¥.	ater Well No. 1		8. Farm o	r Lease Name
George L.	Buckles	Company			Paicht	Water Cumple Wall
3. Address of Operator	MACKICA	Company			9. Well No	Water Supply Well
P.O. Rox 1	45. Mon	ahans, Texas	o 70756			
4. Location of Well	TO A INIOIS	eriono: I CAMI	5 J 7/ JU		10 Field	and Pool, or Wildcat
		90	••			and 1 doly of wildedt
UNIT LETTER	· · ·	FEET	FROM THE	LINE AND 55 F	FEET FROM	mmmm
THE E		0.0	0.4			
1HE	LINE, SE	TION	TOWNSHIP	-S RANGE 37-E	<u> — имрм. //////</u>	
	77777	15. E	Elevation (Show whethe	r DF, RT, GR, etc.)	12. Count	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
				, , , , , , , , , , , , , , , , , , , ,	_	
16.	Chac	Approprieto	Por To I-1	N. C.Y.		(1)
NC	TICE OF	INTENTION TO	o:	Nature of Notice, Repor	t or Other Data EQUENT REPOR	T OF:
					<u> </u>	
PERFORM REMEDIAL WORK	. 🔲		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
	_		PEGG AND ABANDON			
TEMPORARILY ABANDON			PEGG AND ABANDON	COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING			CHANGE PLANS			PLUG AND ABANDONMENT
				COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT
				COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB		PLUG AND ABANDONMENT
PULL OR ALTER CASING	r Completed	Operations (Clearl	CHANGE PLANS	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB		
OTHER 17. Describe Proposed o work) SEE RULE 11 Set 7" Cast Set 10 sacks	Iron Tit	an Bridge, Plu	y state all pertinent de	COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER ails, and give pertinent dates,		
OTHER 17. Describe Proposed o work) SEE RULE 11 Set 7" Cast Set 10 sacks Set Identific	Iron Tit	an Bridge, Plant plug in 7" c	y state all pertinent de	commence drilling opns. casing test and cement JQB other tails, and give pertinent dates, to surface.	including estimated d	