

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-09646
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No. 141560
7. Lease Name or Unit Agreement Name Cooper Jal Unit
8. Well No. 224
9. Pool name or Wildcat Jalmat Tansill

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER <u>Injec</u>	
2. Name of Operator Texaco Exploration and Production, Inc.	
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240-2528	
4. Well Location Unit Letter <u>C</u> : <u>330</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>West</u> Line Section <u>25</u> Township <u>24S</u> Range <u>36E</u> NMPM Lea County	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) 3309 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 5 1/2" CIBP @+-2,950' spot 25 SX plug 2,950' - 2,750'
2. Displace hole with plug mud
3. Spot 30 SX plug 1,375' - 1,100'
4. Spot 10 SX surface plug
5. Install dry hole marker, clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE ENGINEER DATE 12/2/99
TYPE OR PRINT NAME JAMES T. CORBITT ORIGINAL SIGNED BY 915
TELEPHONE NO 608-4438

(This space for State Use)

DEC 14 1999

PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR TEXACO Exploration & Production
LEASENAME _____

SECT 25 TWN 24 S RNG 36 E
FROM 330 N/S L 2310 E/W L
TD: 3230 FORMATION @ TD JALMAT
PBTD: 3230 FORMATION @ PBTD JALMAT

10 SX SURF

MLF

30 SX
PLUG
1100'
1375'

MLF

2750

8 5/8
@ 292
TOC SURF
DV TOOL @ 225
w/ 200 SXS

25 SX PLUG
2950' - 2750'
CIBP @ 2950

5 1/2
@ 2970
TOC

OH PERFS 2970-3230

TD _____

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	8 5/8	292	SURF	VISUAL
INTMED 1	5 1/2	2970	EST	1500'
INTMED 2				
PROD				
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1			PERFS	-
INTMED 2			OPENHOLE	-
PROD				

*REQUIRED PLUGS DISTRICT I

RUSTLER (ANHYD)	
YATES	
QUEEN	
ORAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
OLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOKA	
MORROW	
MISS	
DEVONIAN	

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #3	CIBP	25 SXS	4800'
PLUG #4	STUB	50 SXS	3600'-3700'
PLUG #5	RETNR SQZ	200 SXS	400'
PLUG #6	SURF	10 SXS	0-10'
PLUG #1	CIBP		2950
PLUG #2	YATES	25	2950-2750
PLUG #3	SHOE	30	1375-1100
PLUG #4	SURF	10	10'-SURF
PLUG #5			
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #			
PLUG #			