

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 09661
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	COOPER JAL UNIT
8. Well No.	139
9. Pool Name or Wildcat	Jalmat Tansill Yates 7 Rivers Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3314' KB

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location	Unit Letter <u>B</u> : <u>330</u> Feet From The <u>NORTH</u> Line and <u>2310</u> Feet From The <u>EAST</u> Line Section <u>25</u> Township <u>24S</u> Range <u>36E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3314' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER:	<input type="checkbox"/>		

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPERATION	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER:	<input checked="" type="checkbox"/>	Aban Langlie Mattix Inj , Recomp Jalmat	<input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Objective: Abandon Langlie Mattix injection, recomple to Jalmat production

- 1) Set 5 1/2" CIBP @ 3355', cap w/35' cement, PBTD=3320'
- 2) Perf Jalmat 3014-3222, 8 intervals w/2 JSPF, 252-0.56" holes
- 3) Frac Jalmat w/134 K sand & 36 K gel
- 4) 10-28-93: Pump 57 oil, 330 wtr, 25 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry W. Johnson TITLE Engr Asst DATE 2/14/94

TYPE OR PRINT NAME Larry W. Johnson Telephone No. 397-0426

(This space for State Use)

APPROVED BY Paul Kase TITLE Geologist DATE 2/14/94

CONDITIONS OF APPROVAL, IF ANY: