

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002509669
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 03216
7. Lease Name or Unit Agreement Name Woolworth
8. Well No. 1
9. Pool name or Wildcat Jalmat T-Y-SR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Convest Energy Corporation	
3. Address of Operator 2401 Fountain View Dr., Suite 700, Houston, TX 77057	
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>26</u> Township <u>24S</u> Range <u>36E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Spotted plug #1 w/ 70 sx 3047-2872'. (Tagged)
- 2) Displaced hole w/ 9.0 ppg mud.
- 3) Perfd @ 1394'.
- 4) Spotted plug #2 w/ 35 sx 1394-1141'. (Tagged)
- 5) Perfd @ 235'.
- 6) Spotted plug #3 235'-surface w/ 64 sx.
- 7) Cut off csgs. Welded on dry hole marker.
- 8) Cleaned & leveled location. P&A 9/22/92. ✓

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Theresa Overturf TITLE Engineering Technician DATE 9/30/92
TYPE OR PRINT NAME Theresa Overturf

TELEPHONE NO. (713) 780-1952

(This space for State Use)

APPROVED BY Charlie Barr TITLE DIRECTOR DATE NOV 12 '92

CONDITIONS OF APPROVAL, IF ANY: