

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-09669

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

03216

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Woolworth

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Convest Energy Corporation

8. Well No.

1

3. Address of Operator

2401 Fountain View Dr., Suite 700, Houston, TX 77057

9. Pool name or Wildcat

Jalmat T-Y-SR

4. Well Location

Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 26

Township

24S

Range

36E

NMPM

Lea

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3309 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1) Notify ~~BIM~~ ^{OCD} @ (505) 393-~~3612~~ ⁶¹⁶¹

2) MI & RU rig. POOH w/ Prod. Eqmt. LD all except tbg.

3) GIH & set CIBP @ 3400'±. Spot 35' cement on BP w/ bailer.

4) Displace hole w/ 9.0 ppg mud.

5) Cut & Pull 7" csg @ 1394'.

6) Spot cmt plug from 1394-1294'.

7) cut 9-5/8" csg @ 235'. Spot cmt plug from 235'-surface inside & outside 9-5/8" csg.

8) Cut off csg's 4' below GL. Weld on plate & marker w/ ID plate.

9) Clean & level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Theresa Overturf

TITLE Engineering Technician

DATE 2/28/92

TYPE OR PRINT NAME

Theresa Overturf

TELEPHONE NO. 713/780-1295

(This space for State Use)

RECEIVED BY CERRY GENTON

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 03 '92

RECEIVED

MAR 03 1992

OCD HOBBS OFFICE

WOLWORTH No. 1

TD: @ 3505

Elev: 3309

15 1/2" CSS set @ 185'. Cemented w/ 225 sx

9 5/8" 40-0 # CSS set @ 1344'. Cemented w/ 500 sx

7" 44" CSS set @ 3452. Cemented w/ 400 sx

TD. 3505

42.381 50 SHEETS 1 SQUARE
42.382 100 SHEETS 1 SQUARE
42.383 200 SHEETS 1 SQUARE



RECEIVED
MAR 03 1992
OCD HOBBS OFFICE

RECEIVED
FEB 24 1992
OCD HOBBS OFFICE