CASING PULLERS, INC.

PHONE A/C 505 392-5541 3600 North Turner -:- P. O. Box 105 HOBBS, NEW MEXICO 88240 DATE 7-17-72 CEMENTING AFFIDAVIT PULLING & PLUGGING REPORT COMPANY L.A. Nohnson + French Noclworth #1 LEASE SECTION \_\_\_\_\_ TOWNSHIP \_\_\_\_\_ RANGE \_76 BLOCK \_\_\_\_\_ COUNTY \_\_\_\_\_ \_\_\_\_FT. OF \_\_\_\_\_\_ CASING RECOVERED (0, 1)\_\_\_\_FT. OF \_\_\_\_\_CASING RECOVERED PLUGS SET 1. <u>55</u> SAX CEMENT SET AT <u>3190</u> FT. - TO <u>2750</u> FT. 2. 20 sax cement set at 160 ft. - to 0 ft. 3. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ TO \_\_\_\_\_ FT. 4. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 5. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 6. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 7. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 8. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 9. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 10. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 11. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. 12. \_\_\_\_\_ SAX CEMENT SET AT \_\_\_\_\_ FT. - TO \_\_\_\_\_ FT. CASING PULLERS, INC.

SIGNED Bold Kay - Pushe TITLE VICE PRES. OPERATIONS



JUL 1 1972

DEL CONSERVATION COMM. HOBLS, N. D.



## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION HOBBS DISTRICT OFFICE June 17, 1980

POST OFFICE BOX 1980 HOBBS, NEW MEXICO 88240 (505) 393-6161

BRUCE KING GOVERNOR LARRY KEHOE BECRETARY

> Johnson & French Oil Co. 117 E. Kansas Ave. Jal, New Mexico 88252

Dear Sir,

You reported that your well, the <u>Woolworth No. 1</u>, located in unit <u>H</u>, sec. <u>26</u>, <u>T</u> <u>24</u> <u>S</u>, <u>R</u> <u>36</u> <u>E</u>, was plugged in <u>July 1972</u> Since this date we have received no notification that this well is ready for final surface inspection. If the surface is ready, please notify us. If it is not, clean up this well location as soon as possible, and notify us when the work is completed. The Oil Conservation Division feels that you have had more than adequate time to get this P&A location in shape.

Sincerely,

OIL CONSERVATION DIVISION

John W. Runyan Geogologist