

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate. Following the completion of the plugging a report should be made under "Report on Result of Abandonment of Well" on Form SG-106.

Bartlesville, Oklahoma, N. Mex., January 28, 1935

Mr. E. H. Wells
State Geologist,
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon C. D. Woolworth Well No. 12 in NE 1/4 SW 1/4 of Sec. 26 T. 24S R. 36E, N. M. P. M., Jal Oil Field, Lea County. We plan to commence work on January 23, 1935.

The reasons for wishing to abandon the well are as follows: Surface pipe parted in several places at a depth of 131'.

The present condition of the well is as follows:

Total depth 950' in shale. Surface pipe parted at a depth of 131' and a decision was made to plug well and skid rig.

The work which we propose to do in abandoning the well is as follows:

Fill with cement from the total depth of 950' to the surface.

Approved _____ 19____

Except as follows:

Sincerely yours,

Phillips Petroleum Company
By _____ Company or Operator.

Position Vice President

Send communications regarding this well to

Name C. P. Dimit

Address Bartlesville, Oklahoma


State Geologist or Oil and Gas Inspector.

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate. Following the completion of the plugging a report should be made under "Report on Result of Abandonment of Well" on Form SG-106.

New Mexico, Santa Fe, January 28, 1933

Mr. E. J. Latta,
State Geologist,
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon _____ Well No. _____ in _____ of Sec. _____ T. _____ R. _____ N. M. P. M., _____ Oil Field, _____ County. We plan to commence work on _____, 1933. The reasons for wishing to abandon the well are as follows: _____ places at a depth of 121'.

The present condition of the well is as follows:
Total depth 950' in casing. Casing pipe parted at a depth of 131' and a decision was made to plug well and abandon it.

The work which we propose to do in abandoning the well is as follows:

Will with casing from the top of the well to the bottom.

Sincerely yours,

Approved _____ 1933

Except as follows:

By _____
Company or Operator

Position _____

Send communications regarding this well to

Name _____

Address _____