

(SUBMIT IN TRIPLICATE)

U. S. Land Office Las Cruces

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Lease or permit No. 032618  
I. B. Ogg (b)

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 27, 1943  
I. B. Ogg (b)  
Well No. 1 is located 660 ft. from S line and 660 ft. from E line of Sec. 34  
SE 1/4 of Sec. 34 24 S 36 E 18911  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Cooper Lea County New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3278 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 3513' Line, 7" casing - 3400'.

Desire to treat this well (as approved by phone conversation 7-27-43) with 1000 gallons acid from approximately 3445' to 3505' to increase production. Will spot from 5' to 8' of Jelly Seal in the bottom of the well to attempt to eliminate possibility of acid entering water saturated formation.

Results will be submitted within 10 days after treating.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By [Signature]

Title District Superintendent

BC: NMOcc