

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

Fed LC 032618 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

J.B. OGG "B" #2

9. API Well No.

30025-09688

10. Field and Pool, or Exploratory Area

JALMAT T-Y-SR

11. County or Parish, State

LEA COUNTY
NEW MEXICO

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONVEST ENERGY CORP.

3. Address and Telephone No.

2401 Fountain View, Suite 700, Houston, TX 77057

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit H
1980' FNL & 660 FEL, Sec. 34, T24S-R36E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Notify BLM (SDS) 393-3612
- 2) ME & RU. rig. POOH. w/ Prod. Eqmt. LD. ALL except tubing.
- 3) GIN + Set CIBP @ 3300 ±. Spot 35' cement on BP w/ baler.
- 4) GIN + Displace w/ 9.0 ppg Mud.
- 5) Perf 7" csg @ 1396'. Spot 100' cement plug inside + outside 7" csg. TAG PLUG.
- 6) Perf 9 5/8" csg @ 211'. Spot 100' cement plug from 211-111 inside and outside csg.
- 7) Cut off csg 4' below ground. Weld on plate + ID MARKER.
- 8) Level & RESTORE LOCATION.

CEMENT SLURRY USED IN THIS PROCEDURE SHALL BE CLASS "C"
WITH 2% CaCl₂ MIXED AT 14.8 PPG.

14. I hereby certify that the foregoing is true and correct

Signed

Ed Steinhilber

Title

Agent

Date

7/20/92

(This space for Federal or State office use)

Approved by

Adam S. Carney

Title

Date

8/10/92

Conditions of approval, if any:

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

FED. LC-032618 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

I.B. OGG "B" #2

9. API Well No.

N/A

10. Field and Pool, or Exploratory Area

JALMATT-Y-SR

11. County or Parish, State

LEA Co., NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONVEST ENERGY CORP.

3. Address and Telephone No.

2401 FOUNTAINVIEW Suite 700, Houston, TX 77057

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FNL & 660' FEL, section 34 T24S-R36E

H

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1) NOTIFY BLM @ (505) 393-3612

2) MI + RU Rig. POOH w/ Prod. Egmt. LD ALL EXCEPT TBG.

3) GIW + set CIBP @ 3300' T. SPOT 35' cement on BS w/ bahr.

4) GIW + Circ w/ 9.0 PPG mud.

5) Cut 7" CSS @ 1396'. Pull + LD 7" CSS.

6) SPOT cement plug from 1396-1296 in 9 5/8" CSS.

7) Cut 9 5/8" CSS @ 211'. SPOT cement plug from 211' to surf. inside + outside of 9 5/8" CSS.

8) Cut off CSS 4' below GL. Weld on plate and well marked w/ ID sign.

9) Clean + Level location.

14. I hereby certify that the foregoing is true and correct

Signed

E. L. Greenberg

Title

Agent

Date

2/13/92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

2/26/92

Small scale partial

WELL: I.B. OGG "B" #2

FORMATION: YATES

TID: 3501'

ELEVATION: 3282 G.L

12 1/2" csg @ 161'. Cemented w/175 sx

9 5/8" csg @ 1346'. Cemented w/1000 sx

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
N. M. OIL CONS. COMMISSION
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032618 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

I. B. Ogg "B"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Jalmat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 34, T24S, R36E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR ConVest Energy Corporation	8. FARM OR LEASE NAME I. B. Ogg "B"
3. ADDRESS OF OPERATOR c/o Oil Reports & Gas Services, Inc. Box 763, Hobbs, NM 88241	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 660' FEL of Sec. 34	10. FIELD AND POOL, OR WILDCAT Jalmat
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
12. COUNTY OR PARISH Lea	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) Return to Production

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Swab Test

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/1/84 Ran 2 7/8" tubing to 2970.

3/2/84 Swab 22 bbl oil, 250 bbls water, very small amount of gas. Shut in to check pressure buildup.

An attempt will be made to flow well periodically.



18. I hereby certify that the foregoing is true and correct

SIGNED *William Hobbs*

TITLE Agent

DATE 3/5/84

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY *SWD*
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAY 1 1984

*See Instructions on Reverse Side

Carlsbad, New Mexico

RECEIVED

MAY 18 1984

O.C.D.
HOEBS OFFICE