EW MEXICO OIL CONSERVATION			
UPLICAMISCELLANEOUS REPORTS O	N WELLS		
Submit this report in distance is the Oil Conservation Commission District of		- TATE	

Conservation Commission District Office within ten days after the pork specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well; results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	x		

May 19, 1952 Date Hobos, New Mexico Place

Form C-103

Following is a report on the work done and the results obtained under the heading noted above at the.....

4

~ • • •

Company or Operator	Everett	Well No.	2	
	Lease			
of Sec	.35, T	, R	<u>36-e</u>	, N. M. P. M.,
Cooper-Jal				
The dates of this work were as follows: Marc	h 24 to 29 inclusive			

and approval of the proposed plan was (mer not) ebtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Everett well No. 3 was drilled to a total depth of 3508'. This well was completed in April, 1935. It was temporary abandoned in October, 1951 since production was 100% water.

The well was plugged and abandoned in March, 1952, with the approval of the Oil Conservation Commission. The hole was loaded with mud; 25 sacks of cement was run to plug off open hole and top of cement was found at 3450; recemented with 50 sacks of cement and top of cement was found at 3330' which was satisfactory since casing was set at 3405'. The 7" casing was shot off at 2840' and pulled. Fifty sacks of cement was spotted from 2850' to 2810' and 25 sacks of cement was spotted from 60' to the surface. A 4" marker 4! in height was installed to mark the plugged and abandoned location. 9 5/8" and  $12^{1}_{2}$ " casing were left in the hole.

Witnessed by R. S. Sty Cities Se	company Cistrict Superintendent
APPROVED: OIL CONSERVATION COMMISSION	I hereby swear or affirm that the information given above is true and correct.
Name	Position Jistrict Superintendent
Title	Representing <u>Cities Service Cil Company</u> Company or Operator
Date	Address