NO. OF COPIES RECEIVED				<b>)</b>	Form C-103	
DISTRIBUTION				€	Supersedes	Old
SANTAFE	NE	W MEXICO OIL CON	SERVATION COMMISSION	ON.	C-102 and C	
FILE		MEXICO OIL CON	SEKTATION COMMISSIN	JN .	Effective 1-1	1-65
U.S.G.S.			e, e.		5a. Indicate Typ	on of I ages
LAND OFFICE			Control of the second	i ing	State X	Fee.
OPERATOR					5. State Oil & G	
	<del>-  </del>				B-1167	Loade No.
	SUNDRY NOTICES	ND DEDODIE OL	I WELL C		mm	mmmn
(DO NOT USE THIS FORM	A FOR PROPOSALS TO DRILL APPLICATION FOR PERMIT -	OR TO DEEPEN OR PLUG	I WELLS BACK TO A DIFFERENT RESER CH PROPOSALS.)	VOIR.		
1.	ATTENDATION FOR PERMIT S	(FORM C-101) FOR SU	CH PROPOSALS.)		7. Unit Agreeme	ent Name
OIL A GAS WELL WELL	OTHER-					
2. Name of Operator			·		8 Farm or Leas State A	se Name
Shell Oil Company	7				State A	
3. Address of Operator P.O. Box 1509, Mi	dland Towas -	70701			9. Well No.	
r.o. box 1303, Mi	diand, lexas -	79701			#1	
4. Location of Well					10. Field and P	ool, or Wildcat
UNIT LETTER	1980	south	<b>66</b> 0		Langlie Ma	ttix
			LINE AND	FEET FROM		
east	E, SECTION	248	36E			
LIN	-,,,	IOMNORIP	RANGE	NMPM		
	15, E	levation (Show whether	· DF, RT, GR, etc.)		12. County	.,41111111
		3255 DF			Lea	
16.	Check Appropriate F	Box To Indicate 1	Nature of Notice, Re	nort or Ot	her Data	
	E OF INTENTION TO				T REPORT OF	•
				BOLGOLIA	I KLFOKT OF	•
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		A1 *C	RING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPN	<u>.</u> H		<del>-</del>
PULL OR ALTER CASING		CHANGE PLANS		<del></del>	PLUG	AND ABANDONMENT
oce on Action Choine		CHANGE PLANS	CASING TEST AND CEMENT	10B []		<u></u>
OTHER			OTHER			
OTHER.						
7. Describe Proposed or Comp	oleted Operations (Clearly	state all pertinent des	ails, and give pertinent da	tes, including	estimated date of	starting any proposed
work) SEE RULE 1103.						
1. Pull rods a	nd tbg.					
	_					
2. Took off fl	anges.					
3. Closed in w	ell and rigged	down pulling (	ınit.			
			•			
						•
8. I hereby certify that the infe	ormation above is true and	i complete to the best	of my knowledge and belief	f.		
Week.						
16Ndll asrien	N.W. Harrison	Stai	f Operations Eng	gineer	3~2.	5-69
			100000000000000000000000000000000000000			
1/m	XA)					
PPROVED BY	Maner		in the second		DATE	
	AF ANY:		· · · · · · · · · · · · · · · · · · ·			
CHOITIONS OF APPROVAL,	TE ANT:					

	¬ ·				
NO. OF COPIES RECEIVED		Form C-103			
DISTRIBUTION		Supersedes Old C-102 and C-103			
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65			
FILE	1				
	v£a 1° E c − 11 tag	5a. Indicate Type of Lease			
U.S.G.S.		State 🛣 Fee			
LAND OFFICE	-	5. State Oil & Gas Lease No.			
OPERATOR		B-1167			
		mmmmm <del>m</del>			
SUND	RY NOTICES AND REPORTS ON WELLS TO DETAIL OF TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR.				
(DO NOT USE THIS FORM FOR PR USE **APPLICA	TION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)				
1.		7. Unit Agreement Name			
OIL X GAS WELL WELL	OTHER-				
2. Name of Operator	8. Farm or Lease Name				
Shell Oil Company	State A				
3. Address of Operator	9. Well No.				
P. O. Box 1509 Midland	#1				
4. Location of Well	10. Field and Pool, or Wildcat				
4. Location of well	1980 South 660	Langlie Mattix			
UNIT LETTER	1980 South LINE AND 660 FEET FROM	Transition March			
Pact	26 269 269				
the Line, sect	TION 36 TOWNSHIP 24S RANGE 36E NMPM				
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County			
	3255 DF	Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\			
16. Check	Appropriate Box To Indicate Nature of Notice, Report or Ot	her Data			
	•• •	T REPORT OF:			
401102 01	NT ENTION TO				
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
PERFORM REMEDIAL WORK		<u> </u>			
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT			
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB				
	OTHER				
OTHER					
	Operations (Clearly state all pertinent details, and give pertinent dates, including	a actimated date of starting any proposed			
17. Describe Proposed or Completed ( work) SEE RULE 1103.	perations (Glearly state all pertinent delatis, and give pertinent dates, including	g estimated date of starting and proposed			
,	1-13 thru 2-5-69				
1. Pulled csg. nump.	Dumned frac sand. Plushack from 35221 to 3/51!	Cannad aand			
1. Pulled csg. pump. Dumped frac sand. Plugback from 3522' to 3451'. Capped sand w/hydromite from 3451' to 3421'.					
w/nydromrte from 5	431 CO 3421 .				
0 B-11-1 1					
2. Pulled rods, csg.	pump and tail pipe.				
3. Ran GR/correlation	collar log. Perf 3371, 3373, 3375, 3377, 3379,	3387, 3389 (7 holes)			
3/8" JS. Ran RTTS	Halliburton pkr. on 2-3/8" tbg. at 3353'.				
4. Acidized perfs w/2	000 gal. 15% NE acid and 14 ball sealers.				
	-				
5. Ran 111 Jts 2-3	/8" EUE tbg, hung at 3380'. Ran 2" X 1-1/2" X 1	21 pacific nump			
		- pactic pamp.			
6. Place on production	n.				
o. Hace on production	IA ●				
18. I hereby certify that the informati	on above is true and complete to the best of my knowledge and belief.				
Original Signed By  N. W. Harrison	N.W.Harrison TITLE Staff Operations Engr.	DATE 9 11 60			
signed	N.W.Harrison TITLE Staff Operations Engr.	DATE 2-11-69			
		EFD 4 9 1000			
	CONTRICT OF DESTRICT OF	FEB 13 1969			

CONDITIONS OF APPROVAL, IF ANY: