F	orm	9-331
4	May	1963)

WELL

## BMIT IN TRIPLIC UNITE STATES DEPARTMENT OF THE INTER LOR YED NOT THE YED NOT T

	Form a	approv	eđ.			
	Budget	Bure	au N	o. 4	2–R	142
LEASE	DESIG	NATION	AND	SER	TAT.	NO.

GEOL	.OGICAL	SURVEY

HOBBS, NEW MEXICO

83340 LC-032339(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	---------	-----	---------	----	-------

Water Injection

(1)0 not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7.	UNIT	AGR	EEMEN'	NAME	
1					
1					
1 Q	WADM	ΛÞ	LEASE	MAME	

G. H. Mattix <del>Federal</del>

9. WELL NO.

NAME OF	OFERATOR		
Carter	Foundation	${\tt Production}$	Compan

У 3. ADDRESS OF OPERATOR

OTHER

79745 P. O. Box 900, Kermit, Texas

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)
At surface

660' FSL & 1982' FEL Section 3, T-24-S, R-37-E

10. FIELD AND POOL, OR WILDCAT Langlie Mattix Seven-Rivers Queen 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 3, T-24S, R-37E

14. PERMIT NO. Order No. R-7082

REPAIR WELL

(Other)

GAS WELL

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3240' GR, 3246' DF

12. COUNTY OR PARISH | 13. STATE

New Mexico Lea

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF PULL OR ALTER CASING FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF REPAIRING WELL FRACTURE TREATMENT ALTERING CASING SHOOTING OR ACIDIZING ABANDONMENT\*

(Other) Conversion to Water Injection (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Ran 117 jts. 2" Fiberglass Tubing set at 3393'. Baker Tension Packer set at 3412'. Injection Interval: 3496'-3646'

Injection commenced 10-8-82.

OST 13 1982

CL & EAS MINERALS MEGIT. SERVICE ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct Agent 10 - 8 - 82SIGNED TITLE DATE (This space for Federal or State TED FOR RECORD APPROVED AS COLD DET CONDITIONS OF APPROVAL TITLE DATE Ł

RECEIVED

JAN 19 1983

O.C.D. HOBBS OFFICE

\$ 24 miles 2000 and 100 miles 20