Form	9~331
(Max	1963

DFPAR

		21/11/					
TMENT	OF	THE	INT	ĘRh	DBOX	1980 structions	Θħ

Form approved. Budget Bureau No. 42-R1424.

١,	LEASE	DE	SIGNATION	AND	SERIAL	N(
	-	~	00000	^ /		

ALTERING CASING

ABANDONMENT*

	GEOLOGICAL SURVEYHOBBS, NEW MEXICO 88240	LC-032339(a)
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	OIL X GAS WELL OTHER	7. UNIT AGREEMENT NAME
2.	NAME OF OPERATOR	8. FARM OR LEASE NAME
	Carter Foundation Production Company	G. H. Mattix Baderal
3.	ADDRESS OF OPERATOR	9. WELL NO.
	P. O. Box 900, Kermit, Texas 79745	6
4.	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1982' FEL Section 3, T-24S, R-37E	10. FIELD AND POOL, OR WILDCAT Langlie-Mattix Seven-Rivers Queen 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 3, T-24S, R-37E
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)	12. COUNTY OR PARISH 13. STATE
	3240' GR, 3246' DF	Lea New Mexico
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or O	ther Data
	NOTICE OF INTENTION TO: SUBSEQUI	ENT REPORT OF:
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FRACTURE TREATMENT

(Other)

Change of Lease

SHOOTING OR ACIDIZING

Well is currently shut-in.

Remove tubing and rerun with packer to set at 3400'. 1.

MULTIPLE COMPLETE

ABANDONS

CHANGL PLANS

Acidize with 10,000 gallons 20% acid in stages with blocking material, using 1200 SCF of CO2 per barrel.

Swab test. 3.

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Estimated starting date: 12-5-81

OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

SIGNED Cottly that the foregoing ds true and	d correct Agent	DATE 11-17-81
(This space for Federal or State of Color of Approved & Orig. Sgd.) PETER W. Conditions of Approval, if any: OCT 1 9 15	HESTER TITLE	DATE
FOR JAMES A. GILL DISTRICT SUPER	HAM*See Instructions on Reverse Side	