Form 3160-5 (December 1989)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

5. Lease Designation and Serial No. LC- 032339 A

	_				
6 1	<del>/ 1</del>	adia.	Alleman	or Tribe	

7. If Unit or CA. Agreement Designation

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

I. Type of Well		<del></del>
	8. Well Name and No. Myers	
2. Name of Operator	, · · · · · · · · · · · · · · · · · · ·	
Texaco Exploration & Product	Langlie Mattix Unit #15  9. API Well No.	
3. Address and Telephone No.		30-025-10992
P.O. Box 730, Hobbs, NM 883	10. Field and Pool, or Exploratory Area	
P.O. BOX 730, Hobbs, NM 883  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	oxion)	Langlie Mattix
Unit Letter H, 1980 FNL,	11. County or Parish, State	
Section 3, T-24-S, R-37-E	Lea County, NM	
12. CHECK APPROPRIATE BOX(s) T	O INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF AC	TION
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
- I am Avendonation House		Conversion to Injection
- and roundment rouge	Other	

.

(See Other Side)

	the foregoing is true and correct	Title	Production Engineer	Date _	5/6/92
Approved byConditions of approv	eral or State office use)	Tide	TETROLEUM ENGINEER	Date _	5/13/92

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Rawn

3

## DA&S OIL WELL SERVICING

INCORPORATED

TEXACO EXPLORATION & PRODUCTION MYERS - LANGLIE - MATTIX UNIT #153

- 4/24/92 -MOVE IN, RIG UP, INSTALL B.O.P., PICK UP AND TALLY 2 3/8" TUBING IN HOLE, TAG CEMENT AT 3200', OK BY B.L.M., CIRCULATE MUD, PULL TUBING TO 2431', SPOT 20 SACKS OF CEMENT FROM 2431-UP, PULL TUBING UP, SHUT DOWN.
- TAG CEMENT AT 2300', PLUG FROM 2431'-2300', PULL TUBING OUT, 4/28/92 - -RUN CEMENT BULLDOG, GOOD CEMENT AT 2000', SOME CEMENT UP TO 1600', PERFORATE WELL AT 1200', RUN TUBING IN HOLE TO 1250', PUMP 150 BARRELS MUD, WELL WOULD NOT CIRCULATE, SPOT 75 SACKS OF CEMENT ON BACKSIDE, 7" AT 1200', 25 SACKS OF CEMENT IN 7" FROM 1250'-UP, PULL TUBING, SHUT DOWN.
- TAG CEMENT AT 1160', PULL TUBING OUT, PERFORATE WELL AT 275', 4/29/92 -CIRCULATE WELL TO SURFACE, PUMP 123 SACKS OF CEMENT DOWN 7" TO 275', UP 10 3/4" TO SURFACE, CUT OFF WELLHEAD, INSTALL MARKER, FILL COLLAR WITH CEMENT, RIG DOWN, MOVE OFF.

505-392-6591

P.O. BOX 2545

HOBBS, NEW MEXICO 88241

HOBBS, NEW MEXICO

(505) 392-6591 (915) 523-4420

MIDLAND, TEXAS

EUNICE, NEW MEXICO (505) 394-2557 19151 685-8555