

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SAINT A FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDARY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PUMP BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101, FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☐ Fee ☒ 5. State Oil & Gas Lease No. -----
1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER- 2. Name of Operator Getty Oil Company 3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER <u>B</u> <u>660'</u> FEET FROM THE <u>North</u> LINE AND <u>1980'</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> N.M.P.M.		7. Unit Agreement Name Myers Langlie Mattix Uni 8. Farm or Lease Name Myers Langlie Mattix Uni 9. Well No. 127 10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3328' D.F.		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Recement casing</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- (1) Rig up pulling unit.
- (2) Install BOP and pull tubing and packer.
- (3) Set retrievable BP @ 3300' and test casing.
- (4) Run cement bond log to find top of cement.
- (5) Perforate 2 holes at top of cement.
- (6) Establish circulation down casing and out Bradenhead.
- (7) Pump 50 barrels color-dye plug to determine cement volume.
- (8) Mix sufficient cement to circulate to surface.
- (9) Displace cement within 100 feet of perforations.
- (10) WOC 24 hours.
- (11) Drill out cement and test casing.
- (12) Pull BP.
- (13) Run tubing and packer and put on injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Area Superintendent DATE 2-21-78

Original Signed By
Jerry Sexton
Dist 1, Supv.

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 22 1978

OIL CONSERVATION COMM.
HOBBS, N. M.