

- 1.) MIRU pulling unit. NU BOP. TIH w/ 4 7/8" RB on 2 7/8" tubing and tag PBTD of 3640'. TOOH w/ RB, and tbg.
- 2.) RU Black Warrior WL and run GR/N log. Perforate Queen (3476' - 3595') w/ premium shots 1 JSPF at the following depths: 3476' - 3483', 3566' - 3579', 3586' - 3595'. Total of 32 shots. Depth reference log PGAC Gamma Ray / Neutron log dated January 27, 1962. (See attached strip log)
- 3.) RIH w/ treating pkr on 2 7/8" tubing and set @ \pm 3420. Pressure test csg to 500#. RU Charger, Acidize Queen Perfs (3476' - 3610') w/ 5000 gals 15% Ne Fe HCl containing 2% AS-66 and utilizing rock salt as block. Flush w/ 2% KCl wtr. Swab back load.
- 4.) TOOH w/ pkr and tbg. TIH w/ PC Guiberson G-6 pkr on 2 3/8" FG lined tbg. Circ hole w/ pkr fluid, and set pkr @ \pm 3420'. ND BOP, NU WH. Pressure test annulus to 500# and cut 30 min chart for BLM.

RECEIVED

1964

JO HOBBS
OFFICE