Form 3160-5 (November 1994)

TYPE OF SUBMISSION

☐ Final Abandonment Notice

Notice of Intent

Subsequent Report

Acidize

Alter Casing

Casing Repair

Change Plans

UNITED STATES DEPARTMENT OF THE INTERIOR

N.M. Oil Cons. Division

TYPE OF ACTION

Production (Start/Resume)

Temporarily Abandon

Reclamation

Recomplete

FORM APPROVED OMB No. 1004-0135 Expures July 31, 1996

Water Shut-Off

Well Integrity

Other

1625 N. French Dr. Lease Serial No. BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLOODS, NM 88240 10138170 - NM 7488 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side Myers Langlie Mattix Unit Type of Well Oil Well Gas Well Dother Injection 8. Well Name and No. ミアル Name of Operator OXY USA WTP Limited Partnership 192463 9. API Well No. 30-025- **\\D** 3b. Phone No. (include area code) Address P.O. Box 50250 Midland, TX 79710 915-685-5717 10. Field and Pool, or Exploratory Area Langlie Mattix 7R-Qn-GB 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1960 FUL 1905 FUL SENWLF) SEC STRYS R37E NM Lea 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

Water Disposal ☐ Plug Back Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Deepen

Fracture Treat

Plug and Abandon

New Construction

See other side

Approved as to plugging of the well bore Liability under bond is retained until surface regionation is completed

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart		Title	Title Regulatory Analyst	
Signature	Ou III	Date	ટાપીગ	
	THIS SPACE FOR	FEDERAL OR	STATE OFFICE USE	
Approved by	(ORIG. SGD.) ALEXIS C. SWOBODA		PETROLEUM ENGINEER atc	FEB 20 2001
certify that the	oproval, if any, are attached. Approval of this notice do applicant holds legal or equitable title to those rights in the applicant to conduct operation thereon		Office	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

MLMU # 143

12/4/2000

MIRU Test Anchors. Spot Rig, Pipe Racks, and tbg. Work string. SDON

12/5/2000

ND WH NU BOP. Release pkr and LD 106 jts tbg & G6 pkr. TIH csg scraper 108 jts tbg to 3420. POOH TIH w/CIBP set at 3387. Circ well and test. Leaked. POOH. TIH w/pkr and hunt holes in csg. Holes at 360 to 422. SION

12/6/2000

TIH w/107 jts and pot 45 sks Class C cmt from 3387 to 2750. PU to 2750. Mix and circ 20 sks of salt gel. POOH. RUWL perf @ 1290. RDWL. TIH w/pkr and 32 jts set pkr 1020. Mix and pump 30 sks of Class C cmt and 8.5 bbls displacement. POOH WOC TIH and TOC 1180 w/38 jts POOH. TIH w/ret and 9 jts. SION

12/7/2000

Set pkr @ 290. Mix and pump 100 sks of Class C cmt. 80 on back side to circ to sur. 20 inside csg to fill to surf. LD Tbg. ND BOP. RDPU. Clean and Clear location. Well Plugged.

\$18,400

FIGWELL NN