

- 1.) MIRU pulling unit. NU BOP. TIH w/ 4 3/4" RB on 2 7/8" tubing and tag PBSD of 3606'. TOOH w/ RB and tbq.
- 2.) RU Black Warrior WL and run GR/N log. Perforate Queen (3453' - 3567') w/ premium shots 1 JSPF at the following depths: 3453' - 3461', 3471' - 3475', 3486' - 3493', 3501' - 3505', 3537' - 3545', 3554' - 3567'. Total of 50 shots. Depth reference log Western Gammatron Log. (See attached strip log)
- 3.) RIH w/ PPI pkr on 2 7/8" tubing. RU Charger, Set pkr @ each interval of perfs and break down perfs w/ 20 gals of 15% Ne Fe HCl. PU on pkr to \pm 3370' and pump away remainder of acid for a total of 3000 gals. Flush w/ 2% KCl wtr. Swab back load.
- 4.) TOOH w/ pkr and tbq. TIH w/ PC Guiberson G-6 pkr on 2 7/8" FG lined tbq. Circ hole w/ pkr fluid, and set pkr @ \pm 3370'. ND BOP, NU WH. Pressure test annulus to 500# and cut 30 min chart for BLM.

RECEIVED

NOV 10 1994

COBBS
OFFICE