## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF EGPIES RECFIRED		
DISTRIBUTION		
SANTA FE	1	
PILE		
U.S.G.S.		
LAND OFFICE		
( ) S ( ) + × C >	7	

CONDITIONS OF APPROVAL, IF ANY

## OIL CONSERVATION DIVISION

	-		_
DISTRIBUTION	P. O. BOX 2088		Form C-103
SANTAFE	SANTA FE, NE	W MEXICO 87501	Revised 10-1-7
PILE	_		Sa. Indicate Type of Lease
U.S.G.S.			
LAND OFFICE		•	State Fee X
ROTARDRO	J		5, State Oil & Gas Lease No.
CHAILS	OV NOTICES AND DECODES OF	NUCLAC	THE THE PARTY OF T
AUNUS Det hot magt eint zeu tok ouj	RY NOTICES AND REPORTS OF OPPOSALS TO DRILL OR TO DEEPLE OR PEUG.	YELLS  BACK TO A DIFFERENT RESERVOIR.	
	10H FOR PERMIT -" (FORM C-101) FOR SI	JCH PROPOSALS.)	
1. OIL (			7. Unit Agreement Name
OIL GAS X	OTHER-		
2. Name of Operator ARCO Oil 8	& Gas Company		8. Farm or Lease Name
Division of Atlantic Richfield Company			
Address of Carator			Jim Camp WN
	1710	·	9. Well No.
P. O. Box	1710, Hobbs, New Mexico	88240	2
4. Location of Weil			10. Field and Pool, or Wildcat
E 1	1980 North	660	Jalmat Yates Gas
UNIT LETTER	1980 FEET FROM THE North	LINE AND DOU FEET	FROM TITTELLITES GAS
	_		
THE West LINE, SECTION	ON6	S RANGE 37E	MPM.
	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12. County
	//////		
		17' GR	Lea \\\\\\\\
Check A	Appropriate Box To Indicate	Nature of Notice, Report or	Other Data
	TENTION TO:		ENT REPORT OF:
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		3003290	ENT REPORT OF:
<del>[ ]</del>	<b>_</b>		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	· ·	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL ON ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	\
	•	OTHEN	<u></u>
OTHER Perforate L-M 7 R	Rivers & dual X		
w/Jalmat Gas	-2 V 0 2 0 0 0 0 0 1 ( A)		
•	erations (Clearly state all pertinent de	tails, and give pertinent dotes, inclu	iding estimated date of starting any proposed
work) SEE RULE 1103.	,,		and estimated date of starting any proposed
1. Rig up, kill well,	install BOP & POH w. com	np. assy.	
2. CO to PBD @ 3362'.	Run CBL	•	
3. Perforate 5-1/2" OD c	sg. above TOC as indicat	ed by log Circ Cl C	omt /2% 0 - 01 -1
nerfs to surf WO	C Drill out out CCI	D 6 2200t D	cmt. W/2% Ca CI thru
3575' TD.	C. Drill out cmt. & CIF	or @ 3380 . Press. tes	it csg. Drill out to
עו כוכנ.			
4. Acidize L-M oil zon	e 3450-3575' w/3000 gals	. 15% LSTNE-FE HCL aci	d. Swab load & test
5. RIH w/tubing for L-	M oil zone, produce Jalm	at Gas thru the -cee	annulus as duel oil/se-
well.	, 1		annulus as dual oll/gas
•			
	•		
	_		,
	•		
	·		
	•		
18. I hereby certify that the information	spove is true and complete to the best	of my knowledge and belief.	•
\ 1h ( )			
the me		Dist. Drlg. Supt.	DATE 6-23-80
			DATE 0-23-80
Orlg. Signe	od P		- W
Jerry Sexto	ा ।		<b>JUN 27</b> 1989
APPROVED BY			DATE OUT LANGUE