

Expires August 31, 1985

LEASE DESIGNATION AND SERIAL NO.

NM-7488

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1980' FNL x 1980' FEL (Unit G, SW/4, NE/4)

14. PERMIT NO. 15. ELEVATIONS (Show whether on, at, or etc.)
3321' DF

7. UNIT AGREEMENT NAME

9. FARM OR LEASE NAME
Myers B Federal

9. WELL NO.
10

10. FIELD AND POOL, OR WILDCAT

JALMAT GAS
11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

7-24-37

12. COUNTY OR PARISH 13. STATE
Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WELLS SHUT-OFF ☐ WELL OR ALTER CASING ☐
FRAC TREAT ☐ MULTIPLE COMPLETE ☐
SHUT-OFF AT 1000' ☐ ABANDON ☒
REPAIR ☐ CHANGE PLANS ☐
Other ☐

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT ☐
(Other) ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. (If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and give per cent. to this work.)

Propose to plug and abandon the subject well per the following:

Move in service unit and POH. Run CIBP on tubing and land at $\pm 2810'$ (Top Yates perf at 2860'). Cap CIBP with 25 sx of class C Neat cement. This will bring cement up 150' to 2660'. With tubing place 25 sx of class C Neat cement from 1335'-1185'. This will place cement 75' above and below 9-5/8" casing shoe at 1260'. With tubing place 25 sx of class C Neat cement from 376'-226'. This will place cement 75' above and below 13-3/8" casing shoe at 301'. Spot 10 ~~50~~ surface plug (class C Neat cement). Erect PxA marker and cap well.

*Mud will be placed between all plugs. Minimum consistency must be that obtained by mixing at a rate of 25 sx of gel per 100 bbls. of water.

* Plugs will be in and behind 7" casing
a minimum of 100' in length. P.W.C.

0+6-BLM, R 1-R.E.Ogden, Hou 21.150 1-F. J. Nash, Hou 4.206 1-CMH

1. I hereby certify that the foregoing is true and correct

APPROVED (Signature) TITLE Admin. Analyst DATE 12-20-83

(To be signed for Federal Approval)

APPROVED (Original) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JAN 30 1984

*See Instructions on Reverse Side