


DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS



Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

Shut-in Pressure, Bradenhead Gas Well XX

April 20, 1951

Date

Hobbs, New Mexico

Place

Following is a report on the work done and the results obtained under the heading noted above at the

Skelly Oil Company

Company or Operator

S. E. Toby

Lease

Well No.

1

in the

SW/4 SW/4

of Sec.

7

T.

24S

R.

37E

N. M. P. M.,

Langlie-Mattix

Pool

Lea

County.

The dates of this work were as follows: 4-16-51

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____, 19____, and approval of the proposed plan ~~was~~ (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

24-hour Shut-in Pressure - 727 PSIG.

Witnessed by Fred G. Bernard

Name

El Paso Nat'l. Gas Co.

Company

Engineer

Title

APPROVED:

OIL CONSERVATION COMMISSION

Oil & Gas Inspector

Name

Title

APR 23 1951

Date

I hereby swear or affirm that the information given above is true and correct.

Name

Position

Dist. Supt.

Representing

Skelly Oil Company

Company or Operator

Address Drawer "D", Hobbs, New Mexico

RECEIVED
JAN 10 1964
U.S. AIR FORCE
HEADQUARTERS
AMERICAN AIR FORCE
ATTENTION: AIR FORCE
ATTENTION: AIR FORCE

100-100000-100000

100-100000-100000
100-100000-100000
100-100000-100000