

AMERICAN METER

CHART NO. M-1000-SH
METER

CHART PUT ON

TAKEN OFF

LOCATION

REMARKS

INTEGRITY TEST
SINGER
AMERICAN METER DIVISION




Chart on 4-2-95
 time on 10:00 am
 Chart off 4-11-95
 time off 10:00 am
 leaving gas to America
 Red per 0-1000
 Blue per 0-500
 dry. Trading for oxy gas m.