

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

CIL ☐ GAS ☒ OTHER ☐
WELL ☐ WELL ☒

7. Unit Agreement Name

Name of Operator

Conoco Inc.

8. Farm or Lease Name

Cooper 8

Address of Operator

P. O. Box 460, Hobbs, New Mexico 88240

9. Well No.

1

Location of Well

UNIT LETTER L 1980' FEET FROM THE south LINE AND 660' FEET FROM

10. Field and Pool, or Wildcat

Jalmat Yates Gas

THE West LINE, SECTION 8 TOWNSHIP 24S RANGE 37E NMPM.

11. Elevation (Show whether LF, RT, GR, etc.)

12. County

Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. CO csg to 2800'. Set CIBP @ 2750'. Spot 25 SX class H neat cmt on top of CIBP, TOC @ 2633. Fill hole w/ weighted packer fluid. Spot 25 SX class H neat cmt from 117' to surface. Install P & A marker & clean location.

100' cont plug @ 800'

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John A. Bullerford

TITLE Administrative Supervisor

OCT - 3 1984
DATE 9-25-84