**	-									- FED)] _
								- ~of	E CIE	I VI LEAL	Form C- 104
			· + 71	~ OI	IL CONSERVAT		ISSI	ON 🕂	Second Second		
	191		ATT	د	Santa Fe,	New Mexico		3 *		1 100	
11	UT					v			The .	- NAM	SSLOW
	[Ji	REQUE	ST FOR (OIL) be submitted b ted oil or gas sport Oil) will 04 is to be sub)-(GAS) A	LLO	VABLE	Vira	TION CUMMU	
	مسيا		مستعصد فرطان معطان	e fem	ha aubuddad 1		- +	10	IL CONSER	BS-OF	
It IS :	neces:	sary ioned	to any	complet	ted oil or gas	well. For	ator m C-		Certifi	cate of a	lowable
ance a	nd Au	thori	zation t	o Trans	sport Oil) will	l not be app	p ro v	ed un	til Form	C-104 is	s filed
					es will be reta exico. The all						
					i completion r						
					nat date in the						
into t	he st	ock t	anks. G	ias must	t be reported o	on 15.025 P	•B•	at 60	0 Fahre	nheit.	
	ł	ю в в а,	. N N N N			JANUARY	16,	1951			
			Pl	ace		· · · -	· · · · · ·		Date		
	urnta	ÓV DE				NTI VNOUN					
WE ARE					LOWABLE FOR A V						
	K	MERI	LUTTRELL	•	JACK Lease	Well N	0	1 in	n1	/4	_ 1/4
	-		=								
section	n8		т. 24 S	. R	378 ,N.M.P.M	Langlie-Ma	att1	Pool	Lea		County
		,									
Please	indi	cate :	location	Elev	vation 3310	Spudded	11/2	2/50	Complet	ed_1/9/5	1
·		+	··	T Tota	al Depth3600	,	ם מ				
											·
				Тор	011/Gas Pay	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Тор	Water	Pay	3 /000	D OR CU.FT.
		+			tial production	i Test: Pum	p	F J	LOW		S PER DAY
C					ed on 40 Bb1						_ Mins.
				Meth	od of Test (Pi	tot, gauge	pr.	over. 070.00	meter r	un): 3/30-360	0
				0126	e of choke the t	nenes	¥	••••••	· · · · · · ·		
				Tubi	.ng (Size) 2 "	SUE			3470		Feet
		1		Pres	sures: Tubing	120/	<u> </u>	Cas	$sing - \frac{40}{2}$.0	
				Gas	011, Ratio - :				1VIC <u>V</u>	6 Plus	
				1		Casing Pe	erfo	ratior	n s:		
Unit 1	letter	·:	-						·····		
				Acid	l Record:			Show	of 011,	Gas and w	ater
Casing	& Cer	nenti	ng Recor		Gals			s/	Iatos /	4504=4708 1.42=7567	(Bry Gas) (C11 & Gas)
Size	e I	Feet	Sax		Gals			S/			
10	2/4 .	303	200		Gals						
10-	3/4* :	34 3		Sho	Ots	359 50	90			<u>-</u>	
5-3	1/2" :	3460			Qts			s/	· · · · · · · · · · · · · · · · · · ·		
					Qts			S/			
						400	• 01	1 ^{5/}	•		
					iral Production	•				1.0	
			l	Test	t after acid or	• shot:		Pun	nping	ŀ	lowing
Please	indic	eate l	nelow Ho	rmation	a Tops(in confo	rmance with	h σe	oorant	nical se	ction of	state):
		<u>1130</u>	Southeas	tern Ne	ew Mexico			Northv	vestern	New Mexic	0
T. Anhy	v	1300			Devonian						
T. Sal	۲	200-			Silurian					itland	
B. Sal					Montoya Simpson					ffs	
					McKee						
T. Que	en			Т.	Ellenburger		T.	Menef	fee		
	• • •				Gr. Wash					t	
			. <u>.</u> *		Grapit 3600		_				
T. Dri	nkard			I.	·						
T. Tub	bs			Т.			T.	Penn			······································
I. M1S	s			Т.			T.				

(Please supply required information on reverse side of form)

Date first oil run to tanks or gas to pipe line: To Tanks 1-1-51 -Pipe line taking oil or ###: Texas-New Mexico Pipe Line Company Remarks: As of 1-1-51 - Waiting on Pipeline Connection \$ HOMER LUTTRELL Company or Operator

COUNT EUGENE BLOUNT By:

Position: PRODUCTION SUPT.

Send communications regarding well to:

an an

Name: _____EUGENE BLOUNT

Address: P. O. Box 1163 - Kermit, Texas

¢.

APPROVED <u>JUN - 30</u>, 1951 OIL CONSERVATION COMMISSION By: May C. Junhrallyn Title:

.

· .