



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
DISTRICT I Hobbs
P.O. BOX 1888
Hobbs, NM 88240-1980
1505/ 393-8101

Jennifer A. Salisbury
CABINET SECRETARY

August 12, 1998

Post-It® Fax Note	7671	Date	8/27/98	# of pages	1
To	Donna Pitzer	From	David Stewart		
Co./Dept.	NMOC	Co.	OXY USA Inc.		
Phone #	505-393-6161	Phone #	915-685-5717		
Fax #	505-393-0720	Fax #			

Oxy USA Inc.
P.O. Box 69
Hobbs, NM 88240

RE. ANNUAL BRADENHEAD/PRESSURE TESTING
MYERS LANGLIE MATTIX UNIT

Gentlemen:

An Oil Conservation Division Representative recently witnessed bradenhead and/or pressure testing on wells in the above unit.

The pressure test performed on July 10, 1998, on well #63, located in unit A-36-23-36, show the well is capable of demonstrating mechanical integrity. However, due to a problem with the recorder, a pressure test chart was not obtained. We request that the recorder be repaired, so a chart can be referenced on future testing. Please note that this test will be recorded as being in compliance with OCD rules.

Well #86, located in unit L-34-23-37, failed to perform a pressure test. The test is inconclusive and the valve on the tubing needs to be repaired. The OCD will request a pressure test on this well prior to September 15, 1998. A notification will be submitted by mail or you will be contacted.

Well #194, located in unit A-9-24-37, had fluid on the production casing and would not bleed down. Please make any repairs necessary to correct the problems referenced. Notify the OCD office 24 hours prior to any repairs and testing, so that an OCD representative may be present to witness.

Copies of the test results are enclosed for your information.

Sincerely,

Chris Williams

CHRIS WILLIAMS
District I Supervisor

/s/d

cc: Lori Wrotenbery
file