Wormany group DELVUI WENT OF THE INTERIOR WASHINGTON	MM STIGITUTE AUGUST	31, 1985
BUREAU OF LAND MANAGEMENT	CO1882400-LC	ND <del>SCHO</del> L NO. 032339B
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT" for such proposals.)	& FINDWIN ALLOTTEE OF	
	7. UNIT AGREEMENT NAM	Ē
OT MET OWER OWER	MYERS LANGL	E MATTIX UNIT
OXY USA INC.	8. FARM OR LEASE NAME	
a ADDRESS OF OPERATOR P.O. BOX 50250 MIDLAND, TX 79710	a WELLNO.	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)	10. FIELD AND POOL, ORV	VILDCAT
At surface	LANGLIE MATT	TX 7R Q-G
1980 FNL 660 FEL SENE	11. SEC, T, R, M, OR BU SURWEY OR AREA	
14. PERMIT NO. 15. ELEVATIONS (Show wheter DF, RT, GR, etc.)	SEC 10 T24S	
CONTRACTOR OF A STATE OF THE ST		13. STATE
OLTO	LEA -	NM
Check Appropriate Box To Indicate Nature of Notices, Report, or		
SUBSE	QUENTREPORTOF:	
TESTWATER SHUT-OFF PULL CRALTER CASING WATER SHUT-OFF FINCTURE TREATMENT SHOOT CRACIDIZE ABANDON' SHOOTING CRACIDIZING (Other)	rietaring Altering Abandon	CASING
(Note: Report results of	multiple completion on letion Report and Log fo	Well
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and five pertinent date proposed work. If well is directionally drilled, give subsurface locations and measured and true ver nent to this work.)*	s, including estimated of tical depths for all marks	late of starting any us and zones perti-
TD - 3625' PBTD - 3625' PERFS - 3396'-3625'		
OXY USA INC. REQUESTS TO TEMPORARILY ABANDON THIS WELL FOR FUTURE DE 40 ACRE 5 SPOT PATTERNS.	EVELOPMENT ON	
40 ACRE 5 SPOT PATTERNS.  1) MIRU PU. TIH W/ CIBP & SET @ 3320'.	EVELOPMENT ON	
40 ACRE 5 SPOT PATTERNS.	EVELOPMENT ON	
1) MIRU PU. TIH W/ CIBP & SET @ 3320'.  2) NOTIFY BLM OF CASING INTEGRITY TEST 24HRS IN ADVANCE.		
1) MIRU PU. TIH W/ CIBP & SET @ 3320'.  2) NOTIFY BLM OF CASING INTEGRITY TEST 24HRS IN ADVANCE.  3) RU PUMP TRUCK, CIRCULATE WELL WITH TREATED WATER, PRESSURE TEST C.  18. Thereby couldy that the flooring in the Advance.	ASING TO 500# F	OR 30 MIN.
1) MIRU PU. TIH W/ CIBP & SET @ 3320'. 2) NOTIFY BLM OF CASING INTEGRITY TEST 24HRS IN ADVANCE. 3) RU PUMP TRUCK, CIRCULATE WELL WITH TREATED WATER, PRESSURE TEST CA	ASING TO 500# F	OR 30 MIN.

\*See Instructions on Reverse Side