					Form C+	103
OF LOUIS MICL	V10				Superse	· .
						nd C-103
DISTRIBUTION		NEV MEXICO	OIL CONSERVA	TION COMMISSION	Effectiv	n 1-1-65
TATE			4		p	
Ľ.		3-NMOCC-HOBBS		1-BH, FIELD CLK	-	Type of Lease
.G.S.		1-R. J. STARRAK		1-BB, OFC TECH	Stoto 1	Fee J
IDOFFICE		1-A. B. CARY-MI		1-FILE	5. Store GH	& Gua Lense No.
ERATOR		1-A. B. CARI-MI 1-ELB, ENGR.			B-132	27
				1.0		HUINTINI,
		NOTICES AND DEP	SUST SON AFT	LD SADIFICTUREST RESERVOIR. HUSSIES.)		
IDO NOT USE T	LAL TAPLICATO	STON PLANTS IN TODALC	-101-101-01-01-01-01-01-01-01-01-01-01-0	P353(3.)	7. Unit Aut	evaluation and the second s
WILL X	with L	014ER-			6, Furner	Lease Name
Kane of Gerotor						co "G"
Getty Oil Co	mpany				9. Well No.	
Allress of Operato	1				2	
P. O. Box 730, Hobbs, NM 88240						nd Pool, or Wildow
Location of Nell						signated Fowler
UNIT LEITER	F	2308 FERT FROM THE	West	INE AND 1980 FEET	TROM TTOPPE	T Paddoet XXX
					////	
North		16 TOWNS	NIP 24S	_ RANGE 37E	RINDRO ())	
THE NOT LI	Line, seens				12. County	
THITTITT	TIMININI,	IIII 15. Elevetion (Show whether DF.	K1, 6K, ctc.)		
HHHHHH	illillili		3257' DF		Lea_	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data						
-	NOTICE OF IN	TENTION TO:	1	SUBSEQ	UENT REPORT	OF:
	NOTICE OF IN	, and the second second				r
		PLUG AND	ABANDON RE	MEDIAL WORK		ALTERING CASING
PERFORM REMEDIAL W				MMENCE DRILLING OPHS.		PLUG AND ADANDONNENT.
TEMPERARILY ADANDO		CHANGE PI		SING TEST AND CEMENT JOB		· · · · · · · · · · · · · · · · · · ·
PULL ON ALTER CASH		Change 1		OTHER Plug back as	nd complete i	n_upper_zone IX
OTHER						are of starting any proposed
13 Describe Proposi	ed of Completed Op	erations (Clearly state al	l pertinent details,	and give pertinent dates, in	emang estimated a	ate of stations of the
ついかんたうたた だいしり	1. 110 .					
8-27-79 R	iaaed up Gen	e's Well Service	e and pulled	rods and pump. I	nstalled BOP	and pulled tog.
8-28-79 R	Ran 4 $1/2$ " 16	ad impression bl	Lock - indic	ated parted csg. a	t 2558'. Mi	lled, fished,
to s	swaged, graps	pled, washed, and	d cleaned fr	om 2558-5450'.		
10-3-79	Jina 300.7 J= 11	· ·				
					404 20001	d found top of
10-4-79 F	Ran CI plug a	at 5425'. Dresse	er Atlas ran	cement bond log 5	424-3000° an	a round cop or
10 1 / 2	cement at 329	90'.				
			×		0 1 1	
10-5-79 Dr	resser Atlas	perforated 5194	,98,99, 5204	,09,12,14,20, & 24	$1^{\circ} - 9$ notes.	Jumped So
10 0 10 2	ement on plu	q at 5425'. Set	pkr. at 505	9' and acidized wi	th 1000 gais	. 13% NE delu
ai	nd 20 ball s	ealers.				
						Acuilough perfo-
10-10-79 Pi	ulled tbg. a	nd pkr. Hallibu	rton set EZ	drill bridge plug	at 5160°. \mathbf{F}	loc Dumped
ra	ated at 5058	,60,70,72,77,80,	88, 2 holes	at 90, and 92' - 1	10 (.40) 10	.es. Dumped
2	sxs of ceme	nt at 5131'.				
					a pottod 100	Lale 15% NE
10-11-79 R	an pkr. to 5	090'. Runco loa	ded hole wi	th 2% KCl water and	u sporred 100	yuis. 190 ML
					E. •	
	di a the information	(CONT	ete to the best of a	y knowledge and belief.		
1a. Thereby certify	Anon the anonioardi					_
			Ar	ea Superintendent	DATE	12-10-79
SIGNED _ F	- Croclat	X				
<u> </u>						DEC 1 8 1979
	•	igned by			UATE	
APPROVED BY	Jerry Se	exton	1 ITLC			
CONDITIONS OF A	PPROVAL DISt Ja	Anba'				

10-12 to 10-14-79 Swabbing and flowing.

- 10-15 to 10-17-79 Made unsuccessful attempt to latch onto csg. at 3200' with 83 jts. (3192') 5 1/2" with Bowen csg. bowl.
- 10-18-79 Pulled 5 1/2" csg. Recovered 16' of 5 1/2" csg. in csg. bowl. Dressed off top of 5 1/2" csg. 3616-3216.5'.
- 10-19-79 Ran 84 jts. (3208') 15.5# LT&C 8rd and latched on to cut-off csg. at 3216.5'. Ran Bowen bowl. Installed wellhead.
- 10-20-79 Ran retrieving tool. Pulled bridge plug.
- 10-22-79 Ran Baker Loc-Set pkr. on 161 jts. (4984') 2 3/8" tbg. Set pkr. at 4998' with 10,000# tension. SN at 4993'. Ran 2" x 1 1/4" x 16' pump and 136 - 3/4" and 62 - 7/8" rods.
- 10-23-79 Rigged down unit. Pumping, no test (all water).
- 10-24 to 10-29-79 Pumped and tested.
- 10-30-79 Tied in gas sale line to El Paso. 10 $1/2 \times 64$ SPM, 3 BO & 58 BW.
- 11-27-79 Moved in pulling unit. TOH with rods, pump, 161 jts. 2 3/8" tbg, SN, and locset pkr. TIH with 2 3/8" tbg., RTTS, and retrievable BP. Left swinging at 4950'.
- 11-28-79 Set retrievable BP at 4950'. Tested to 1500 psi with pkr. at 4927'. Circulated
 2 sxs sand on top. Found hole in 5 1/2" csg. 3323-54". Csg. bowls at 3216'.
 Set RTTS at 2982'. Pumped and broke circulation with 348 bbls. water.
- 11-29-79 Halliburton cemented with 360 sxs Halliburton lite with 15# salt, 5# gilsonite, 1/4# flocel, and 2% CaCl; followed with 200 sxs Class "C", 5# gilsonite, 1/4# flocel, and 3% CaCl. Mixed 360 sxs lite and cement circulated. SD and mixed 200 sxs Class "C". Displaced cement to 3100'. Circulated 210 sxs.
- 11-30-79 TOH with RTTS. Ran 4 3/4" bit and 6 3 1/2" drill collars. Drilled 16' bridge
 2981-97'. Drilled cement 3090-3334'. Circulated clean. Tested to 1000#, held.
- 12/1/79 TOH with bit. Laid down bit and drill collars. Ran retrieving tool to 4940'. Circulated sand off of BP. Pulled BP at 4950'. TIH with 2 3/8" tbg. 165 jts. (5096') with 15' mud anchor. Set tbg. at 5130' with SN at 5114'. Tbg. anchor at 4958'. Installed head.
- 12-3-79 Ran 2 3/8" x 1 1/4" x 16' pump, 6' mud anchor, and 164 3/4" rods and 68 7/8"
 rods. Hung well on.

12-9-79 24-hr. test - 12 x 64 SPM. 14 BO, 58 BW, & 40 MCFG from perfs. 5058-5092'.

RECEIVED

RECEIVED

DEC 19 179 DIL CONSERVATION DIV

OIL CONSERVATION DIV.

DEC 1 3 1979