

DISTRIBUTION

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-103
Effective 1-1-65

SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

3-NMOCC-HOBBS 1-ELB, ENGR.
1-R. J. STARRAK-TULSA 1-FILE
1-A. B. CARY-MIDLAND

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
B-1327

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR APPLICATION TO OIL & GAS LEASES TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO PRODUCE OIL & GAS FROM A DIFFERENT RESERVOIR.")

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator
Getty Oil Company
3. Address of Operator
P. O. Box 730, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER F 2308 FEET FROM THE West LINE AND 1980 FEET FROM
North 16 TOWNSHIP 24S RANGE 37E
THE LINE, SECTION TOWNSHIP RANGE

7. Unit Agreement Name
8. Form or Lease Name
Mexico G
9. Well No.
2
10. Field and Pool, or Wildcat
Fowler Upper Yeso
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3257' DF16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER Plug back and complete in upper zone ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit and pull rods and pump.
2. Install BOP and pull tubing.
3. Set EZ drill retainer at 5450' and squeeze Fowler Upper Yeso perforations 5433-5567'.
4. Run Cement Bond Log 5450-2000'.
5. Selectively perforate the Fowler Upper Yeso from 5299-5392'.
6. Acidize with 2000 gallons 15% NE acid.
7. Swab test.
8. If well swabs dry, fracture treat with 24,000 gallons Cross Linked gel containing 36,000 lbs. 20/40 sand.
9. Run tubing, pump, and rods and place well on production pumping Fowler Upper Yeso perforations 5299-5392'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Area Superintendent DATE May 22, 1979APPROVED BY Jerry Sexton ORIG. SIGNED BY Jerry Sexton TITLE Dist 1, Supv. DATE MAY 24 1979

RECEIVED

MAY 23 1979

OIL CONSERVATION COMM.
RUBBS, H. M.