

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

042 — P.O. BOX 1980
HOBBS, N.M. 88240 (LEA COUNTY)

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR NOTICES TO WELL OR TO REPORT ON WELLS TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL OR TO RE-ENTER A WELL FOR SUCH PURPOSES.		5a. Indicate Type of Lease State ☐ Fee ☒
1. Name of Operator Getty Oil Company		5. State Oil & Gas Lease No.
2. Address of Operator P. O. Box 730, Hobbs, New Mexico 88240		7. Unit Agreement Name
3. Location of Well UNIT LETTER L 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 24S RANGE 37E N.M.P.M.		8. Form or Lease Name Dalport - Hair
15. Elevation (Show whether DF, RT, GR, etc.)		9. Well No. 1
12. County Lea		10. Field and Pool, or Wildcat

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:		1-R.J. STARRAK-TULSA 1-A.B. CARY-MIDLAND RE 1-E. Buttross, ENGINEER CO 1-H.C. Little, FOREMAN - MLMU CA 1-FILE Q- _____, WIO's -LIST ATTACHED 1-BH, FIELD CLERK
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER Reenter & replug ☒	PLUG AND ABANDON ☐ CHANGE PLANS ☐	☐ ☐ ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

According to the NMOCC Order No. 460 for the expansion of our Myers Langlie Mattix Unit, this well must be properly plugged before water can be injected within a 1/2 mile radius. We plan to reenter and replug the well using the following procedure:

1. Rig up pulling unit and install BOP.
2. Drill out cement plugs surface-60', 990'-1100', and 2680'-2800'.
3. Tag plug at 3980'.
4. Circulate hole with 10# mud.
5. Spot 30 sxs. cement plug 3600-3700' over base of Queen formation.
6. Spot 60 sxs. cement plug 3200-3400' over top of Queen formation.
7. Spot 60 sxs. cement plug 2700-2900' over top of Yates formation.
8. Spot 30 sxs. cement plug 1018-1118' over 8 5/8" casing shoe at 1068'.
9. Spot 15 sxs. cement plug surface-50'.
10. Set marker.

THE COMMISSION MUST BE NOTIFIED
24 HOURS PRIOR TO COMMENCING WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Area Superintendent DATE 8-17-78

APPROVED BY *[Signature]* TITLE Area Superintendent DATE AUG 21 1978

CONDITIONS OF APPROVAL, IF ANY, SIGN