

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
-----	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plugback		7. Unit Agreement Name
Name of Operator		8. Farm or Lease Name
Phillips Petroleum Company		C. D. Woolworth
Address of Operator		9. Well No.
Room 401, 4001, Penbrook, Odessa, Texas 79762		18
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>C</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>2310</u> FEET FROM		Jalmat-Seven Rivers-Oil
THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>24-S</u> RANGE <u>36-E</u> N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3335' RKB		Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Plugback and recomple</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-17-80 MI Tyler DD Unit. Pulled 2-3/8" tbg and Reda pump. Set 2-3/8" tbg w/Howco cmt retainer at 3050'. Pulled out of retainer--circ hole clean. Pressed csg to 1500#, O.K. Pmpd 35 sxs Cl "H" cmt into retainer. Air 2 BPM, max press 2000#. Pulled out of retainer, circ hole w/3% KCL wtr, circ out 1 sx cmt.

Jalmat Seven Rivers oil zone effectively cemented and abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Mueller TITLE Senior Engineering Specialist DATE April 22, 1980

Orig. Signed BY

Jerry Sexton

Date 1. 1980

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 24 1980

CONDITIONS OF APPROVAL, IF ANY: