

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

Santa Fe, New Mexico 87504-2088

API NO. (assigned by OCD on New Wells)
30-025-25463
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name S.J. CARR
8. Well No. 9
9. Pool name or Wildcat LANGLIE MATTIX

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>L</u> : <u>1980'</u> Feet From Th <u>SOUTH</u> Line and <u>510'</u> Feet From The <u>WEST</u> Line Section <u>10</u> Township <u>24S</u> Range <u>37E</u> NMPM <u>LEA</u> County 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3266 GE	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO:

P & A MUD WILL BE PLACED BETWEEN ALL CEMENT PLUGS.
POOH WITH PACKER. SET CIBP AT 3260' SPOT 760' CMT F/3260-2500.
SPOT 400' OF CMT. F/1310-910'.
SPOT 362' OF CMT. TO SURFACE.
CUT OFF WELLHEAD AND INSTALL P & A MARKER.
CHANGE WELL STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT

DATE: 5/7/92

TYPE OR PRINT NAME P.R. MATTHEWS

TELEPHONE NO (915)687-7812

APPROVED BY DISTRICT SUPERVISOR TITLE DISTRICT SUPERVISOR

CONDITIONS OF APPROVAL, IF ANY:

DATE

MAY 11 '92