Submit 3 Copies To Appropriate District Office District I	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			WELL API NO. 30-025- 75949 5. Indicate Type of Lease	
District III 2040 South Pacheco 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE S		
District IV Santa Fe, NM 8/505			6. State Oil & C		
2040 South Pacheco, Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit AgreementName:	
1. Type of Well: Oil Well  Gas Well  Other				MYERS LANGLIE MATTIX UNIT	
2. Name of Operator OXY USA WTP Limited Partnership 192463				8. Well No.	68
3. Address of Operator				9. Pool name or Wildcat	
P.O. BOX 50250 MIDLAND, TX 79710-0250			LANGLIE MATTIX 7RVR-QN-GB		
4. Well Location					
Unit Letter 7: 1980 feet from the South line and 1980 feet from the Fast line					
Section 5 Township 245 Range 37 E NMPM County LEA					
10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
				SEQUENT REI	
PERFORM REMEDIAL WORK		v 🗆	REMEDIAL WORK		ALTERING CASING
		_			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST ANI CEMENT JOB	D 🗆	ADAINDONMENT
OTHER:			OTHER:		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.					
MLMU-168					
NOTIFY NMOCD OF INTENT TO P&A 12/6/00. MIRU PU 12/7/00, RDWH, NU BOP. RIH & SET CIBP @ 3387', CIRC HOLE W/ 9.5#MLF, SPOT 25sx CMT, WOC. RIH & TAG @ 3100', POOH TO 2970', SPOT 25sx CMT, WOC. RIH & TAG CMT @ 2720', POOH TO 1280', SPOT 25sx CMT, WOC. RIH & TAG CMT @ 1028', POOH TO 570', SPOT 60sx CMT TO SURFACE. RDPU 12/14/00. DUG OUT CELLAR, CUT OFF WH & ANCHORS, INSTALL DRY HOLE MARKER, CLEAN LOCATION, WELL P&A'D.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
	41		·	•	_11
SIGNATURE for S	4	_TITLE	REGULATORY A	NALYST	DATE 3/22/01
Type or print name DAVID S	STEWART			Teler	phone No.915-685-5717
(This space for State use)	<u> </u>			<u></u>	
APPPROVED BY Conditions of approval, if any:	ah!	_TITLE	flokes		DATE <u>2-20-03</u>
GWW					

IC