Form 3160-5 (November 1994)	UNITED STA		N.W. U	I Cons. Div	FORM APPROVED OMB No. 1004-0135	
/	DEPARTMENT OF TH	LE INTERIOR	1625 N	French D	C. Expires July 31, 1996	
SUNDE	AND TICES AND RE		Hobbs.	NM 88240	S. Lease Senal No.	
BUREAU OF LAND MANAGEMENT Hobbs, NM 88240 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an					8910138170 - NM	
abandoned w	vell. Use Form 3160-3 (A	APD) for such pr	ropo sa is.		6. If Indian, Allottee or Tribe Nar	ne
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No MYERS LANGLIE MATTIX UNIT	
Oil Well Gas Well	Other				8. Well Name and No.	1100
2. Name of Operator OXY USA Inc.						
10090				9. API Well No. 30-025- 2748(10. Field and Pool, or Exploratory Area 37		
3a. Address P.O. BOX 50250 3b. Phone No. (include area code) MIDLAND, TX 79710-0250 915-685-5717						
4. Locauon of Well (Footage, Sec	c., T., R., M., or Survey Descrip				LANGLIE MATTIX 7 R	
1980 FSL 760 FWL NWSW(L) Sec 4 T245 R37E				37E	11. County or Parish, State LEA NM	
12. CHECK AI	PPROPRIATE BOX(ES)) TO INDICATE	NATURE	OF NOTICE, R	LEPORT, OR OTHER DATA	
TYPE OF SUBMISSION	· · · · · · · · · · · · · · · · · · ·			OF ACTION		
Notice of Intent	Acidize	Deepen		Production (Star	rt/Resume) 🔲 Water Shut-Off	
Subsequent Report	Alter Casing	Fracture Tr		Reclamation	Well Integrity	
	Casing Repair Change Plans	New Const		Recomplete	U Other	<u> </u>
Final Abandonment Notice		Piug and A	bandon 🖌	Temporarily Al	Dandon	
Attach the Bond under which i following completion of the in- testing has been completed. F	the work will be performed or volved operations. If the opera- inal Abandonment Notices shi	provide the Bond N ation results in a mul	uding estimate ce locations ar o. on file with	Water Disposal d starting date of a nd measured and tr BLM/BLA. Requ	iny proposed work and approximate d ue vertical depths of all pertinent mar ired subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and t	kers and zo within 30 (
Attach the Bond under which i following completion of the inv	ed Operation (clearly state al) ectionally or recomplete horizo the work will be performed or volved operations. If the opera- final Abandonment Notices sha	pertinent details, incl ontally, give subsurfa provide the Bond ation results in a mul	uding estimate ce locations ar o. on file with	Water Disposal d starting date of a nd measured and tr BLM/BLA. Requ	ue vertical depths of all pertinent mar ired subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and t	kers and zo within 30 (
Attach the Bond under which it following completion of the inv testing has been completed. F determined that the site is ready TD- <u>3755</u>	ed Operation (clearly state all ectionally or recomplete horizo the work will be performed or volved operations. If the opera- inal Abandonment Notices shi for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u>	uding estimate ce locations ar o. on file with tiple completi r all requireme 3-3109	Water Disposal d starting date of a nd measured and tr BLM/BIA. Required on or recompletion ents, including rech <u>DIER</u> /C	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3444	kers and zo within 30 (
Attach the Bond under which in following completion of the mu- testing has been completed. F determined that the site is ready OXY USA INC. FUTURE PLANS USE THIS WELL	ed Operation (clearly state all j ectionally or recomplete horizo the work will be performed or volved operations. If the oper- rinal Abandonment Notices sha for final inspection.) PBTD- <u>3319</u> ' REQUESTS TO EXTE ARE TO REVIEW TH L FOR WATER INJEC	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> END THE TEMP(IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY DRARILY D PATTER ASSED A	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl 	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3414 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST +:	kers and zo within 30 (
Attach the Bond under which it following completion of the in- testing has been completed. F determined that the site is ready TD- <u>3755</u> OXY USA INC. FUTURE PLANS	ed Operation (clearly state all petionally or recomplete horize the work will be performed or volved operations. If the oper- rinal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> ND THE TEMPO IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY D PATTER ASSED A	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl 	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3414 ATUS APPROVAL. WOULD ALLOW US TO	kers and zo within 30 (
Attach the Bond under which in following completion of the mu- testing has been completed. F determined that the site is ready OXY USA INC. FUTURE PLANS USE THIS WELL	ed Operation (clearly state all petionally or recomplete horize the work will be performed or volved operations. If the oper- rinal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> END THE TEMP(IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY D PATTER ASSED A	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl 	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3414 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST +:	kers and zo within 30 (
Attach the Bond under which it following completion of the inv testing has been completed. F determined that the site is ready TD- <u>3755</u> OXY USA INC. FUTURE PLANS USE THIS WELD <u>1011678</u> .	ed Operation (clearly state all jectionally or recomplete horizo the work will be performed or volved operations. If the oper- inal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> ND THE TEMPO IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY D PATTER ASSED A 2 2 2000 C	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl 	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3414 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST +:	kers and zo within 30 (
Attach the Bond under which it following completion of the in- testing has been completed. F determined that the site is ready TD- <u>3755</u> OXY USA INC. FUTURE PLANS USE THIS WELD <u>1011678</u> .	ed Operation (clearly state all jectionally or recomplete horizo the work will be performed or volved operations. If the oper- inal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> ND THE TEMPO IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY D PATTER ASSED A	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl d d d starting date of a not measured and tr BLM/BIA. Requ on or recompletion ents, including recl d d d starting date of a not measured and tr BLM/BIA. Requ d d tr BLM/BIA. Requ d d tr BLM/BIA. Requ d tr CASING INT.	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3444 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST F:	kers and zo within 30 c
Attach the Bond under which it following completion of the in- testing has been completed. F determined that the site is ready TD- <u>3755</u> OXY USA INC. FUTURE PLANS USE THIS WELD <u>1011678</u> .	ed Operation (clearly state all j ectionally or recomplete horizo the work will be performed or inal Abandonment Notices sha y for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> ND THE TEMPO IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement 3-3109 DRARILY D PATTER ASSED A 2 2 2000 C	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl with the start PHR/C ABANDON ST. N AND THIS CASING INT SASING INT REGULATO	URY ANALYST	kers and zo within 30 (
At the proposal is to beep in the Attach the Bond under which it following completion of the in- testing has been completed. F determined that the site is ready OXY USA INC. FUTURE PLANS USE THIS WELL 10/16/78.	ed Operation (clearly state all performed or pectionally or recomplete horize the work will be performed or volved operations. If the oper- rinal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> END THE TEMPO IE WATERFLOOI TION. IT PA BROWERS FOR STION. IT PA	uding estimate ce locations ar o. on file with tiple completion r all requirement B-3109 DRARILY D PATTER ASSED A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Water Disposal d starting date of a not measured and tr BLM/BLA. Requ on or recompletion ents, including recl " " <u>PHR</u> /C ABANDON ST. N AND THIS CASING INT " " " " " " " " " " " " " " " " " " "	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3444 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST F: O DRY ANALYST	kers and zo within 30 c
At the proposal is to beep in the Attach the Bond under which it following completion of the in- testing has been completed. F determined that the site is ready OXY USA INC. FUTURE PLANS USE THIS WELL 10/16/78.	ed Operation (clearly state all performed or pectionally or recomplete horize the work will be performed or volved operations. If the oper- rinal Abandonment Notices sha for final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS- <u>3466</u> ND THE TEMPO IE WATERFLOOI TION. IT PI	uding estimate ce locations ar o. on file with tiple completion r all requirement B-3109 DRARILY D PATTER ASSED A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Water Disposal d starting date of a nd measured and tr BLM/BIA. Requ on or recompletion ents, including recl d measured and tr BLM/BIA. Requ on or recompletion ents, including recl d measured and tr BLM/BIA. Requ D M/BIA. Requ Area Area Area Area Area Area Area Area	URY ANALYST	kers and zo within 30 (il be filed o he operator
A the proposal is to be performed that Attach the Bond under which it following completion of the invitesting has been completed. F determined that the site is ready OXY USA INC. FUTURE PLANS USE THIS WELD 10/16/78.	ed Operation (clearly state all jectionally or recomplete horizo the work will be performed or volved operations. If the oper- inal Abandonment Notices sha of final inspection.)	pertinent details, inclontally, give subsurfa provide the Bond N ation results in a mul all be filed only after PERFS-3466 END THE TEMPO IE WATERFLOOI TTION. IT PA DECARGINGT COMPANY AND AND AND AND END THE TEMPO IE WATERFLOOI TTION. IT PA DECARGINGT COMPANY AND	uding estimate ce locations ar o. on file with tiple completion r all requirement DRARILY D PATTER ASSED A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Water Disposal d starting date of a not measured and tr BLM/BLA. Requ on or recompletion ents, including recl " PHR/C ABANDON ST. N AND THIS CASING INT AND THIS CASING INT BARCES REGULATO L C E OFFICE USI	ue vertical depths of all pertinent mar irred subsequent reports shall be filed in a new interval, a Form 3160-4 sha amation, have been completed, and the IBP-3444 ATUS APPROVAL. WOULD ALLOW US TO EGRITY TEST F: O DRY ANALYST	kers and zo within 30 d il be filed o be operator